

Yates Petroleum Corporation  
Sacahuiste KE Federal No. 1 NM 9194  
Section 34-22S-23E - Eddy Co., NM  
660' FSL & 1980' FFL

(Continued from page 1)

at 9076'. Broke formation at 4500#. Treated perforations 9150-52' w/1000 gallons 15% DS-30. Swabbed and swabbed 200' of acid water per hour. TD 10106'; PBTD 9725'/ Loaded hole and removed wellhead. Installed BOP's, unseated packer and retrieved RBP at 9212'. Reset RBP at 8960'. POH w/tubing and packer. WIH w/casing gun on wireline and perforated 8864-8932' w/16 .50" holes as follows: 8864-69' (10 holes), 8929'-32' (6 holes) (2spf). WIH w/Baker Lok-Set packer on 2-7/8" tubing set packer at 8828'. Treated perforations w/1500 gallons 15% DS-30 acid and ball sealers. Swabbed. No shows. WIH and set RBP at 8360'. WIH w/casing gun on wireline and perforated 8313-8318' w/10.50" holes (2spf). WIH w/Cuiberson Uni VI packer on 2-7/8" tubing, set packer at 8291' and treated perforation w/1200 gallons 20% DS-30 acid. Well cleaned up and flowed 203 MCFPD, FTP 138# on 1/4" choke. Reacidized perforations 8313-8318' w/5000 gallons 7½% acid and CO-2. No increase in production. TD 10106'; PBTD 8360'.

RECEIVED

SEP 12 1960

U.S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT