

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-0486483

RECEIVED

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

APR 28 1980

7. UNIT AGREEMENT NAME

O.C.D.

8. FARM OR LEASE NAME

ARTESIA, OFFICE

Shell Federal Com

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Cementary Marrow Field

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 8, T-21-S,

R-24-E

12. COUNTY OR PARISH

Eddy

13. STATE
N. Mexico1. OIL WELL ☐ GAS WELL ☒ OTHER2. NAME OF OPERATOR
Durham Inc.

3. ADDRESS OF OPERATOR

P.O. Drawer 273 Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FNL & 2010' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3865' KB, 3856' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIEP at 3400 ft. called and recieved permission from USGS office to set plug high. Capped plug with 5 sacks of class H cement.
2. Circulated hole with mud laden fluid.
3. Cut 5½" casing at 7700ft. pull out of hole with 5½" casing.
4. Run tubing to 7750 and spotted a 50 sack plug wait on cement overnight and taped plug at 7535'.
5. Spotted plugs at 6720' - 50 sacks 5000' - 50 sack, 3280' - 75 sacks and waited on cement for 5 hours.
6. Taped plug at 3070 ft.
7. Cut off well head placed 10 sack surface plug installed dry hole marker and moved off.

RECEIVED

AUG 31 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICOPosted
ID 2
5-2-80
FHA

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Plug & Abandonment Cont.

DATE

August 8, 1979

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.