

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-171	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name	
TXO Production Corp. ✓ 1-915-682-7992	Catclaw Draw St. Com.	
3. Address of Operator	9. Well No.	
900 Wilco Bldg. Midland, TX 79701	1	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 21-S RANGE 26-E NMPM.	Catclaw Craw (Strawn)	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3311 GR	Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-25-85 RU Crawford Well Service. Rlsd Psi. Tbg on vac. Rlsd pkr.
 7-26-85 Set CIBP @8990 w/37sx "C" cmt. Set 25sx "C" plug @7996.
 7-27-85 Removed WH. Weld on 4 1/2" csg stub.
 7-28-85 SI for Sunday.
 7-29-85 RU Jacks. Worked pipe. Had 4300' free pipe. Pipe free to 5400. Cut csg @5325
 Pull 130 jts 4 1/2" csg w/45,000# over string wt.
 7-30-85 TIH w/2 3/8 tbg to 6010. Set 25sx "C" plug @ 6010. Set 35sx "C" plug @5378. Set 35 sx "C" plug @4216. Set 35sx "C" plug @ 2604. Set 35sx "C" plug @557. Set 10s "C" plug @ surface. Weld on dry hole mtkr. Well P & A'd

→ TAGGED AT 2481

pers. comm. w/
Alicia Henderson. LB.

Post ID-2
8-9-85
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alicia Henderson TITLE Engr. Asst. DATE 8-1-85

APPROVED BY Ramp Brooks TITLE Geologist DATE 8-28-85

CONDITIONS OF APPROVAL, IF ANY: