

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

RECEIVED

APR 30 1991

WELL API NO. 30-015-22938
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1798
7. Lease Name or Unit Agreement Name South Soapberry AIH State
8. Well No. 1
9. Pool name or Wildcat Undes. Carlsbad Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3311' GR

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RE-ENTRY <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210

4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 18 Township 21S Range 26E NMPM Eddy County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Perforate, Treat, Swab <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-26-91. Make cut off on 5 1/2" casing. TIH w/bit, collars and 2-7/8" tubing. Tag top of cement at ± 4101'. Perforated 3883-3948' w/12 - .50" holes as follows: 3883, 85, 86, 87, 91, 92, 93, 94, 3945, 46, 47 and 3948'. Acidized perms w/3000 gals 7 1/2% NEFE acid in 2 stages + ball sealers.

3-28-91 - 3-39-91. Swabbed well

3-30-91. Set RBP at 3200' and tested to 1500 psi. Perforated 3122-24' and 3128-41 w/17 .50" holes (1 SPF). Acidized perms 3122-3141' w/2000 gals 7 1/2% NEFE HCL + 32 ball sealers. Swabbed dry.

4-2-91. Moved RBP to 2708' and tested to 1500 psi. Perforated 2654-2661' with 1 SPF - 8 holes. Acidized perms 2654-61' w/1000 gals 7 1/2% NEFE acid and 16 ball sealers.

4-3-91. TP 25#. Fluid level 900'. Swabbed 13 bbls - swabbed dry. No shows. RDPU.

4-21-91. SITP 22# and CP 0#. Blew down to 0 in 30 seconds.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Juanita Goodlett TITLE: Production Supervisor DATE: 4-28-91

TYPE OR PRINT NAME: Juanita Goodlett TELEPHONE NO.: 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY: MIKE WILLIAMS SUPERVISOR, DISTRICT II

APPROVED BY: \_\_\_\_\_ DATE: MAY - 6 1991

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_