O. OF COPIES RECEIVED		RECEIVED		Form (C-103 sedes Old -	
DISTRIBUTION				C-102	and C-103	
NTAFE	11-1	NEW MEXICO OUS CONSE	RVATION COMMISSION	Effect	live 1-1-65	
E	1111	MUU P		Sa. Indice	ile Type of Lease	
s.G. S .		.O. C. D.		State		
ND OFFICE	<u> </u>	ARTESIA, OFFICE			Oil 6 Gas Lease No.	
ERATOR		Militaria		T_	.3534-2	
	SUNDOW MOTH	CEC AND DEDODIE ON V	JCI I C			
(DO NOT USE THIS FOR	SUNUKY NUTTO	CES AND REPORTS ON V	E TO E BIT FERENT RESERVEIN	· (
USE	APPENDATION FOR PE	mail = Viole Caloly is seen		7. Unit A	greement Name	
OIL X GAS WELL	OTHER	•				
Came of Operator .					B. Fam or Leuse Name	
Maralo, Inc. ✓					N.W. Indian Basin Comm.	
diress of Operator				9. Well N	ь.	
P. O. Box 832, M	idland, Texas	79702 0832		10 Field	and Pool, or Wildcat	
OCCITION OF WELL UNIT LETTER K 2310 FEET FROM THE SOUTH LINE AND 2450 FEET FROM					cat	
UNIT LETTERK	2310	FEET FROM THE South	LINE AND	FEET FROM	mmmn	
West Line, SECTION 2 TOWNSHIP 21-S RANGE 22-E NAPH.						
THE West L	INE. SECTIONZ	TOWNSHIPZI-2	RANGE ZZ LI	- NMPM.		
mmm	mmm	15. Elevation (Show whether D	F, RT, GR, etc.)	12. Coun	iy Allilli	
		ì	149.4 GL	Edo	dy ()	
	Chale Assess	iate Box To Indicate Na		rt or Other Data		
	Check Appropr CE OF INTENTION		subs	EQUENT REPOR	RT OF:	
NOTIC	JE OF INTENTIO	JN TO.		-	• _	
REFORM REMEDIAL WORK	1	PLUG AND APANDON	REMEDIAL WORK		ALTERING CASING .	
MPORARILY ABANDON	วี		COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT	
LL OR ALTER CASING	1	CHANGE PLANS .	CASING TEST AND CEMENT JOE	, [_]		
	-		OTHER			
OTHER						
D. J. D. and or Co.	malated Chercians	(Clearly state all pertinent detail	ils, and give pertinent dates,	, including estimated	date of starting any propose	
work) SEE RULE 1103.	impreted Operations (
		·		of anamation	a	
1. Notify NMOCC	Director and	USGS Engineer to per	rmit their withess carior mud laden f	1 operations	•	
RUPU. Displa	ice fluid in n	nole $w/9.5\#/gal$ or he	eavier mud raden r	ruru.		
2. Set CIBP @ 42	200' with 35'	cement on top.				
2. Set OIDI (42	100 . Witch 33				•	
3. Place 25 sack	cement plug	from 1450' to 1350'	•			
			•			
4. Place 25 sack	cement plug	from 450' to 350'.				
		at aurface				
5. Place 15 sack	c cement prug	at surface.			•	
6 Clean up loca	ation commens:	urate with area. Se	cure surface opera	tor (rancher)	approval.	
o. Clean up 10ce	Teron commens		•	-		
				•	•	
		•				
		•				
	information shows is	true and complete to the best o	f my knowledge and belief.			
. I hereby certify that the	/ ^					
\bigcap	(), 00	Ann an an 1	Agent	DATE	8-26-82	
HED SYLM	wa ou	TITLE	0			
	/	1			AUG 3 0 1982	
W/	. Willia	TITLE 01	L AND GAS INSPECTION	time to witness ATE		
PROVED BY		Notify 1	LAND GAS INSPECTION N.M.O.C.C. in sufficient	,,	-	
HIDITIONS OF APPROVA	IL, IF ANY:		1 399119			