Form 9-331	11.11.O.C	D. COPY -	0.21
(May 1963)	DEPARIMENT OF THE INTER	SUBMIT I SIPLICATES	Budget Burean No. 42 R1424 5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		NM-27918
(1)3 not us	SUNDRY NOTICES AND REPORTS • this form for proposals to drill or to deepen or plug Use "AUPLICATION FOR PEPMIT" for such	ON WELLS back to a different reservoir. propositis.)	6. IF INDIAN RECEIVED CLIBE NAME
	AS ELL S OTHER		7. UNIT ACREERID 21 8 1980
	Petroleum Corporation	APR 7-3 (10)	8. FARM OR PEASE YALL SO.AVATESIA MAFIFEd. CC.
207 SOU	ith 4th Street-Artesia, NM	88210 A. L	9. WELL NO. 1
At surface	7 below.) FEL of Sec. $14-2$		10. FIELD AND POOL, OR WILLYCAT WILLYCAT 11. SEC., T., R., M., OL BLE, AND SUBVEY OR ABEA SC. 14-21S-26E
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F. RT. (R. etc.)	Unit I MMPM 12. COUNTY OF PARISH 13. STATE
16.	Check Appropriate Box To Indicate N	Vature of Natice, Report or C	
	NOTICE OF INTENTION TO:		
TEST WATER SH FRACTURE TREAT SHOOT OR ACIDE REPAIR WELL (Other)	T MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE THEATMENT SHOOTING OR ACIDIZING (Other)	ENT REPORT OF: REPAIRING WELL ALTERING CASING ABANDONMENT* of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSE proposed work nent to this wo	ED OR COMPLETED OPERATIONS (Clearly state all pertinen If well is directionally drilled, give subsurface locat rk.)*	t details, and give pertinent dates, tions and measured and true vertical	including estimated date of starting any 1 depths for all markers and zones perti-
TD 11400'; 11164-1118 70, 71, 74 WIH w/pack	PBTD 11349'. WIH w/casing 0' w/12 .50" holes (1 shot .75, 76, 77, 78, 79 & 80'. er set at 11160 and treated	gun on wireline a at each interval) Swabbed well wø tu Perforations w/19	and perforated 11164, 65, 66,

acid and nitrogen w/ball sealers. Well cleaned up and flowed 60# on $\frac{1}{2}"$

POH w/tubing. WIH w/tubing and RBP, set plug at 11050'. Perforated on wireline 10948-54'w/12 .50" holes (2spf). POOH. WIH w/Baker Lok-Set packer on 2-7/8" tubing, set packer at 10938'. Swabbed dry. Treated perforations w/1000 gallons $7\frac{1}{2}$ % MS acid and nitrogen. Flowed well back and well cleaned up and stabilized at 2004 on 1/2" choke.

Set Pkr at 10876'. WIH w/Tubing Conveyed gun and Baker Lok-Set packer on 2-7/8" tubing, set packer at 10876'. Perforated 10908-10914' w/24 .50" holes. No GTS. Pulled guns and packer out of hole. WIH w/packer on 2-7/8" tubing, set packer at 10882'. Treated perforations w/1000 gallons $7\frac{1}{2}$ " MS acid. No increase in production. Appears to be same zone. Opened perforations 10908-10954' and well cleaned up and flowed 175# on 1/2" choke = 1100 MCFPD.

18. I hereby certify that the foregoing is true and correct SIGNED Contract of SIGNED	Geol. Secty.	DATE 4-22-80
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	K STURE	DATE 35 320

*See Instructions on Reverse Side