Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-015-23253	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 ~	Santa Fe, New Mexico 8788420692		5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brizos Rd., Aztec, NM 87410	APR 2 2 1992		6. State Oil & Gas Lease No.	
·····			NM0374057	
SUNDRY NOTICES AND REPORTS ON WELLS FOR OFFIC? (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OL OAS WELL 1 WELL X	OTHER		Catclaw Draw Unit	
2. Name of Operator Hallwood P	etroleum, Inc.		8. Well No. 12	
3. Address of Operator		9. Pool name or Wildcat		
P.O. Box 3	78111 Denver, CO 80237	7	Catclaw Draw Morrow	
4. Well Location Unit LetterN:990	Feet From TheSouth	Line and1980		
Section 24	Township 21S Rang		NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10,440'				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
			SEQUENT REPORT OF:	
		REMEDIAL WORK		
	CHANGE PLANS	COMMENCE DRILLING		
PULL OR ALTER CASING		CASING TEST AND CE		
OTHER:		OTHER: Recomple	ete to Morrow "A"	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
<u>P</u>	LEASE SEE ATTACHED.			

I hereby certify that the information above is true and complete to the best of my knowledge SKONATURE	mne Sr. Engineering Technician April 10, 1992
TYPE OR PRINT NAME Debi Sheely	TELEPHONE NO(303) 850-6207
(This space for State Use)	
APPROVED BY	TITLE DATE

Catclaw Draw Unit #12 Unit N Section 24 T21S R25E Eddy County, New Mexico

MIRUSU, ND Tree, NU 5K BOP, Rls Baker Loc-Set pkr, tally out with tubing. RU Wedge Wireline. RIH and correlate setting depth, set 5 1/2" CIBP @ 10,440', cap plug with 15' sand, new PBTD @ 10,425'. TIH with tubing and guns. TIH with 4 3/4" bit and scraper, test 2 3/8" tbg to 7,000 PSI, land tubing @ 10,400'. NU Rowland Trucking & circ hole with 250 bbl 2% KCL fresh with pkr fluid. Test csg and CIBP to 1500 PSI, held for 30 min, OK. TOH w/tubing. TIH with copact TCP system, 4" guns, mech dis, ported sub, Guiberson 5 1/2" Unit VI with 1.87" PF nipple w/ on-off, 1 jt tbg. TIH w/tbg. RU Wedge Wireline. TIH w/gamma ray & CCL. Load tubing with 8 bbl of 2% KCL fresh w/CLA-STA. Set Guiberson UNI II pkr. RU Western Co. NU to csg. and pressure to 1500 psi, 1400 psik, begin pumping 1500- gal 7 1/2& HCl acid @ 1.8 BPM w/1.2 SCF N2 PM @ 4200 PSI, ISIP 3700, 5-2800, 10-2300, 15-2000, ND service company, beginning FTP 1400 PSI. Well quit unloading fluid and died. RIH with swab and tag fluid @ 3,000', swab all day, fluid scattered 6-8' flare, well did not kick off. Open well on 14/64" choke, well blew down in 45 min. Zone is non -commercial, will not sustain any measurable gas production.