

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRII
(Other instructions
verse side)

ATE

Budget Bureau No. 1004-1
Expires August 31, 1985

clsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAY 14 1992

O. C. D.
APPROVAL OFFICE

8910115880

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM-0374057-A

7. UNIT AGREEMENT NAME

Catclaw Draw Unit

8. FARM OR LEASE NAME

9. WELL NO.

12

10. FIELD AND POOL OR WILDCAT

Catclaw Draw Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 24 T21S R25E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

10,440

12. COUNTY OR PARISH

Eddy

13. STATE

NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Recompletion to Morrow "A"

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Please See Attached.

**** Attachment revised per instructions from Adam Salameh ****

18. I hereby certify that the foregoing is true and correct

SIGNED

Debi Sheely

TITLE Sr. Engineering Technician

(303)850-6207
DATE 5/11/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

CATCLAW DRAW UNIT #12
UNIT N SECTION 24 T21S R25E
EDDY COUNTY, NEW MEXICO

Move in rig up service unit, ND tree, NU 5K BOP, Release Baker Loc-Set Packer, tally out with tubing. RU Wedge Wireline. RIH and correlate setting depth, set 5 1/2" CIBP @ 10,440', cap plug with 15' sand, new PBTD at 10,425'. TIH with 4 3/4" bit and scraper, test 2 3/8" tbg to 7,000 psi. NU and circ hole with 250 bbl 2% KCL fresh with packer fluid. Test csg and CIBP to 1500 psi, held for 30 minutes, OK. TOH with tubing. TIH with 4" guns, mech dis, ported sub, Guiberson 5 1/2" Unit VI packer with 1.87" PF nipple with on/off tool. TIH. Set packer at 10,321', Perforated 10,396' - 10,404' at 4 spf. Acidize with 1500 gal 7 1/2% HCL acid at 1.8 BPM with 1.2 SCF N2 per minute at 4200 psi, ISIP 3700, 5-2800, 10-2300, 15-2000, ND service company, beginning FTP 1400 PSI. Well quit unloading fluid and died. RIH with swab and tag fluid @ 3,000', swab all day, Fluid scattered 6-8' flare, well did not kick off. Open well on 14/64" choke, well blew down in 45 min. zone is non-commercial, will not sustain measurable gas production.