

EST

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Hallwood Petroleum, Inc.

3. Address and Telephone No.
P. O. Box 378111, Denver, CO 80237
(303) 850-6257

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT N 990' FSL & 1980' FWL
SECTION 24-T21S-R25E SESW

5. Lease Designation and Serial No.

NM - 0374057

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

CATCLAW DRAW UNIT

8. Well Name and No.

Catclaw Draw #12

9. API Well No.

30-015-23253

10. Field and Pool, or Exploratory Area

Catclaw Draw

11. County or Prish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Plug & Abandon

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Hallwood plug & abandoned this well 2/3/00 thru 2/9/00, following these prodcedures:

Set a 5 1/2", 17 # CIBP @ 9600', capped CIBP w/ 35' cmt. Set retainer @ 7900' pumped 60 sx neat cmt, 4 bbls fresh water spacer, displace w/ brine. Dump 6 sx cmt on top of retainer. Cut csg @ 5000', pump 100 sx cmt w/ 2% CaCl "stub plug" @ 5000'. TIH w/ tbg, tag "stub plug" @ 4748'. Pump 75 sx cmt w/ 2% CaCl "shoe plug". Tag cmt @ 1878', pump 50 sx same cmt per Duncan Whitlock (BLM). TIH to 400', pump 115 sx same cmt to surface plug. Top off csg w/ cmt & fill cellar to cover top of 13 3/8" csg stub. Cut off and remove wellhead. Install dry hole marker (5 1/2" x 6') directly on 8 5/8" csg. Well P & A'd.

Note: Per Pete Chester w/ BLM - Roswell District, Hallwood was given verbal permission on 2/8/00 to eliminate a Bone Springs cement plug @ approximately 4300'.

Post R/H 4-21-00

14. I hereby certify that the foregoing is true and correct

Signed

Nonyah K Durham

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Nonyah K Durham
Production Reporting Supervisor

Title

Date 02/18/00

APPROVED
PETER W. CHESTER

MAR 27 2000

BUREAU OF LAND MANAGEMENT
ROSWELL DISTRICT
ROSWELL, NM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States, any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED
2009 FEB 22 A 9 41
U.S. DEPT OF LAND HOUS
ROOSEVELT OFFICE