

8. Notify the Survey by telephone 24 hours prior to spudding well.
9. Notify the Survey in sufficient time to witness the cementing of the 4-1/2" casing.
10. Cement behind the 8 7/8" and 4-1/2" casing must be circulated.
11. It is required that a Gamma-Ray-Neutron log be run in open hole from the base of Salado to the surface at a speed not to exceed 30 feet per minute.
12. Please have anyone contacting the Survey in regard to this well to identify the well with all of the information required above for the well sign.

Sincerely yours,

JWS

James W. Sutherland
Oil and Gas Supervisor, SRMA

Enclosure

cc:

Regional Manager, Denver

Mining Branch (2)

BLM, Roswell (w/cy Notice)

NMOCD, Artesia (2) (w/2 cys Notice)

Artesia

Roswell (w/cy Notice)

Area (potash)

Area (chrono.)

District (potash)

District (chrono)