

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
RECEIVED

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. 127 32-834457	
2. NAME OF OPERATOR Jake L. Hamon		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 611 Petroleum Building, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1930'- FSL & 690' FEL of Sec. 33		8. FARM OR LEASE NAME Federal	
14. PERMIT NO.		9. WELL NO. 1-	
15. ELEVATIONS (Show whether DF, RM, OR, ETC.) 3280' Gr. 3296' KB		10. FIELD AND POOL, OR WILDCAT Springs Morrow	
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-20-S, R-26-E	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) Plug back & recomplate ☒		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Well now completed as Morrow Gas Well through perf. from 10,021' and 10,383'. The Morrow zone has watered out and depleted. Propose to plug back and test Strawn and Bone Springs as follows:

1. Set CIBP above Morrow perforations at 10,000' and dump 4 sacks of cement (35') on plug.
2. Perforate Strawn from 9326' to 9356'. Swab test and acidize with 3,000 gals. of acid. Swab back and test. If test indicates additional treatment is necessary, then sand frac Strawn and swab back frac job.
3. In productive, put well on production. If non-productive, plug back and test Bone Spring as following:
4. Run tubing in hole open ended to 9325'. Set 35 sack cement plug from 9325' back to 9025'. Pull tubing up to 5800'. Set 25 sack cement plug from 5800' to 5575'.
5. Perforate Bone Spring from 5198' to 5208'. Swab test and acidize with 1000 gals. Swab test. If non-productive,
6. Set CIBP at 5180' and dump 4 sacks of cement on plug.
7. Perforate Bone Springs from 4996' to 5034'. Swab test and acidize with 2000 gals. Swab test.
8. If productive, put well on production.
9. Estimate work to begin approximately 7/1/83.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Production Engineer DATE 6/24/83

(This space for Federal or State Approval)
APPROVED BY (Orig. Sgd.) PETER W. CHESTER TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUL 7 1983

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.