

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Santa Fe	
File	
BLM	
Land Office	
B of M	
Operator	
WELL APT NO.	

Form C-103
Revised 1-1-89

30-015-23437

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG-5995

7. Lease Name or Unit Agreement Name

Lancaster Spring Unit

8. Well No.

9. Pool name or Wildcat
Happy Valley Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

JUN 22 '89

2. Name of Operator
Amoco Production Company

O. C. D.
ARTESIA, OFFICE

3. Address of Operator
P.O. Box 3092 Houston, TX 77253

4. Well Location
Unit Letter I : 2310 Feet From The South Line and 660 Feet From The East Line

Section 8 Township 22-S Range 26-E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR 3414'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RU Mask Truck x Install Lubricator
2. Run gauge ring or sinker bars to check clearance
3. Perforate with thru thg gun at 4 JSPF with decentralized gun at 0 degree phasing:
10857'-10861'
10874'-10884'
10890'-10904'
11053'-11059'
11096'-11102'
4. Flow to test (if necessary, ru swab unit)
5. Return to production

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Amelia Hartman TITLE Asst. Admin. Analyst DATE 6-20-89
TYPE OR PRINT NAME Amelia Hartman TELEPHONE NO. (713) 584-7

(This space for State Use)

APPROVED BY Johnny Robinson TITLE OIL AND GAS INSPECTOR DATE _____
CONDITIONS OF APPROVAL, IF ANY: