NEW MEXICO OIL CONSERVATION COMPLEXION DRAWER DD ARTESIA, NEW MEXICO

					• · · · · · · · · · · · · · · · · · · ·
Operator Eagle Oil	t Ges Co	Lease Little Indi	an Basin	Well #	1
Location	Upit Section	Townsk	1	County Edd	
Drilling Contractor	Moranco	Type	of Equipment Rotary	(Oct 1,	1981
* Witness	>	_	1		
	APPROV	ED CASING PRC	OGRAM		
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cemen
	13%	48 [#]		450'	Circ
12/4	8 5/8 "	24 [#]		z400'	LIFL
י'אי ר	4 1/2 "	11.6#		9300'	985 SX
Casing Data:	· · · · · · · · · · · · · · · · · · ·				14 /
Suríace	joints of 855 i	nch_2& #	Grade 3-55		
	(Approv	ed) (Rejected	1)		
nspected by	BW WEAVER		date	12/4/81	
Cementing Pro	gram			1 (
ize of hole					
AND OF HOTE	IZ 4 Size of C	asing 857a S	acks coment r	required	270 Sxs thru 1".
			acks coment r	-	1700 INITAL
ype of Shoe	used <u>Guioe</u> Float c	ollar used IN	<u>54.</u> Btm 3 jt€	welded	1700 INITAL
'ype of Shoe 'D of hole_2	used <u>GUIDE</u> Float c <u>420 Set 2429</u> Fee	ollar used inch t of 8% Inch	<u>54 </u> Btm 3 jts 24 [#] Grade	welded	fro INITIAL
'ype of Shoe 'D of hole <u>2</u> lew- used csg.	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee @ <u>2428</u> with <u>2</u>	ollar used <u>ine</u> t of <u>8%</u> Inch oo_sacks ne	<u>s</u> ∔Btm 3 jts 24_ [#] Grade_1 at cement arc	welded (~55 ound sho	fro INITAL
ype of Shoe D of hole <u>2</u> lew- used csg. <u>1300</u> sax	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee @ <u>2428</u> with <u>2</u> Howco Lite	ollar used IN- t of g % Inch o sacks ne additives 20	54_Btm 3 jts 24_ [#] Grade_ at cement arc 20 5rs +hic.	welded (~55 ound sho	fro INITIAL
ype of Shoe D of hole <u>2</u> Wew- used csg. (300_sax Tug down @	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>@2428</u> with <u>2</u> <u>Howco Lize</u> <u>7:30</u> (PM)	ollar used <u>Ave</u> t of <u>85%</u> Inch <u>oo</u> sacks ne additives <u>20</u> Date <u>12/4</u>	5+Btm 3 jts 24_ # Grade 1 at coment arc 50 SKS + hic. 81	welded (~55 ound sho	fro INITAL
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee @2428 with 2 <u>Howco Live</u> <u>7:30</u> (PM) ated <u>No</u>	ollar used <u>INA</u> t of <u>85%</u> Inch <u>oo</u> sacks ne additives <u>20</u> Date <u>12/4</u> No. o	5+ Btm 3 jts 24 [#] Grade at coment arc 50 5ks +hic. 81 f Sacks -	welded 	1700 INITAL fes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>1320</u> sax lug down @ ement circul	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>Q428</u> with <u>2</u> <u>Howco Live</u> <u>1:30</u> (PM) ated <u>No</u> <u>HALLIBURTON</u>	ollar used IN- t of 85% Inch o sacks ne additives 20 Date 12/4 No. o Withe	54_Btm 3 jts 24 [#] Grade 1 at cement arc 50 5×5 thic. 31 1 Sacks - ssed by B.w.	welded	1700 INITAL Jes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul emented by emp. Survey	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lite</u> <u>1:30</u> (AM) (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>21130</u> (AM) (PM)	ollar used ING t of 8% Inch o sacks ne additives 20 Date 12/4 No. o Withe M) Date 12/4	54_Btm 3 jts 24 [#] Grade 1 at cement arc 50 5×5 thic. 31 1 Sacks - ssed by B.w.	welded	1700 INITAL Jes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul emented by emp. Survey	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lire</u> <u>1:30</u> (AM) (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>21130</u> (AM) (Pi (AM) (Pi	ollar used IN- t of 85% Inch o sacks ne additives 20 Date 12/4/ No. o Withe M) Date 12/4/	34 # Grade 24 # Grade at coment are at coment are at coment are b 5x 81 f Sacks ssed by B.W. (s) top com	welded	1700 INITAL Jes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Live</u> <u>1:30</u> (PM) ated <u>No</u> <u>HALLIBUETON</u> ran <u>21:30</u> (AM) (Pi	ollar used <u>INA</u> t of <u>85%</u> Inch <u>oo</u> sacks ne additives <u>20</u> Date <u>12/4</u> No. o Witne M) Date <u>12/4</u> N) Date <u>12/4</u> N) Date <u>12/4</u>	34 # Grade 24 # Grade at coment are at coment are at coment are b 5x 81 f Sacks ssed by B.W. (s) top com	welded	1700 INITAL Jes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lire</u> <u>1:30</u> (AM) (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>21130</u> (AM) (Pi (AM) (Pi	ollar used ING t of 85% Inch additives_20 Date_12/4 No. o Witne M) Date 12/4/ M) Date Witne Witne	34 Btm 3 jts 24 [#] Grade 1 at comment arc bo 5x + hic. 81 1 Sacks - ssed by B.w. (s1 top comment ssed by	welded	1700 INITAL Jes e
ype of Shoe D of hole <u>2</u> lew- used csg. <u>(300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used heckcd for s ethod used	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>ated</u> with <u>2</u> <u>Howco Lire</u> <u>1:30</u> (AM) (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>1:30</u> (AM) (Pi hut off <u>a</u> (AM)	ollar used ING t of 8% Inch o sacks ne additives 20 Date 12/4 No. o Witne M) Date 12/4 W) Date Witne) (PM) Date Witne	34 # Grade at cement are at cement are at cement are b 5 81 f Sacks ssed by B.w. ssed by B.w. ssed by S.w. ssed by S.w. ssed by S.w. ssed by S.w.	welded	1700 INITIA L Jes e
ype of Shoe D of hole <u>2</u> lew-used csg. <u>1300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used heckcd for s ethod used emarks: <u>Fiu</u> ,	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lire</u> <u>1:30</u> (AM) (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>11:30</u> (AM) (Pi hut off <u>(AM)</u> (AM) <u>1 loss <u>685</u> 2 8</u>	ollar used ING t of 85% Inch additives_20 Date2/4/ No. o Witne M) Date2/4/ M) Date Witne) (PM) Date Witne S40 . Fluid	s+Btm 3 jts 24 [#] Grade <u>1</u> at cement arc bo sk< thic. 81 f Sacks - ssed by <u>B.w.</u> /si top cem ssed by ssed by leve (@ 463'	welded (-ss ound sho set. weaver	1700 INITIA L Jes e
ype of Shoe D of hole <u>2</u> lew-used csg. <u>1300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used heckcd for s ethod used emarks: <u>Flu</u> , <u>CMT. BASKETS</u>	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lite</u> <u>1:30</u> AM (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>11:30</u> AM (Pi (AM) (Pi hut off <u>(AM)</u> (AM) <u>1 loss $(abc) = 685 = 2$</u> <u>2 800 $(abc) = 550'$</u>	ollar used INA t of 8% Inch additives ac Date 12/4/ No. o Withe M) Date 12/4/ N) Date 12/4/ N) Date Withe Withe Storf Fluid	Btm 3 jts 24 # Grade 1 at cement are at cement are 5 = 5 + c + hic. 31 f Sacks - ssed by B.W. 261 top ceme ssed by ssed by 1 = 26 C 463	welded	1700 INITIAL fro c
ype of Shoe D of hole <u>2</u> lew- used csg. <u>1300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used heckcd for s ethod used emarks: <u>Flu</u> , <u>CMT. BASKETS</u> :30 <u>PM. 12/4/</u>	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lite</u> <u>1:30</u> AM (PM) ated <u>No</u> <u>4ALLIBURTON</u> ran <u>11:30</u> AM (Pi (AM) (Pi hut off <u>(AM)</u> (Pi <u>1.130</u> (AM) (Pi <u>1.130</u>	ollar used INA t of 8% Inch o sacks ne additives 20 Date 12/4/ No. o Withe M) Date 12/4/ N) Date 12/4/ N) Date Withe Withe S40 . Fluid 5 cent] As	Btm 3 jts 24 # Grade 1 at cement arc at cement arc bo 5x + bic. 31 f Sacks - ssed by B.W. 161 top ceme ssed by ssed by ssed by ssed by 162 $ac + bic5353$ $ac + bic53$ $ac + bic$	velded	1700 INITIAL fro 6 6 6 6 10'. TAGGED
Ype of Shoe D of hole <u>2</u> New-used csg. <u>1300</u> sax lug down @ ement circul emented by emp. Survey asing test @ ethod Used heckcd for s ethod used cmarks: <u>Flui</u> <u>CMT. BASKETS</u> :30 <u>PM. 12/4/</u> N/11'@ 603	used <u>GUIDE</u> Float c <u>420</u> Set <u>2429</u> Fee <u>2428</u> with <u>2</u> <u>Howco Lite</u> <u>1:30</u> AM (PM) ated <u>No</u> <u>HALLIBURTON</u> ran <u>11:30</u> AM (Pi (AM) (Pi hut off <u>(AM)</u> (AM) <u>1 loss $(abc) = 685 = 2$</u> <u>2 800 $(abc) = 550'$</u>	ollar used INA t of 8% Inch additives 20 Date 12/4/ No. o Withe M) Date 12/4/ M) Date 12/	Btm 3 jts $\frac{14}{24}$ = Grade 1 at coment arc $\frac{14}{24}$ = Grade 1 at coment arc $\frac{16}{24}$ = $\frac{16}{24}$ $\frac{16}{24}$ = $\frac{16}{24}$ = $\frac{16}{24}$ $\frac{16}{24}$ = $\frac{16}{24}$ = $\frac{16}{24}$ $\frac{16}{24}$ = $\frac{16}{24}$ = $\frac{16}{$	s welded <u>(-ss</u> bund sho <u>se t</u> <u>wenver</u> ent (w <u>to TDC 6</u> <u>sk. ciec</u>	1700 INITIAL fro e GIO' IO'. TAGGED PUMPED A

*

١

٠·