

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Union Oil Company of California ✓
3. ADDRESS OF OPERATOR
P. O. Box 671 Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☒

(other) Plug & Abandon

5. LEASE

NM-14324

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

RECEIVED

8. FARM OR LEASE NAME

Federal "FI"

DEC 2 1982

9. WELL NO.

1

O. C. D.

10. FIELD OR WILDCAT NAME

Wildcat Artesia Office

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 35 T-21-S R-31-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3,504.7' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4,455' Casing Record: 3-3/8" CD 24' 4,375'

10-5-81 Plug #1 - 455 ex Class "C" cement @ 4,452' - top of cement 3,000'
Plug #2 - 150 ex Class "C" cement @ 3,000' - top of cement 2,716'
Plug #3 - 100 ex Class "C" cement @ 2,716' - top of cement 2,249'
Plug #4 - 100 ex Class "C" cement @ 2,249' - top of cement 1,664'
Plug #5 - 200 ex Class "C" cement @ 1,664' - top of cement 1,170'
Plug #6 - 200 ex Class "C" cement @ 1,170' - top of cement 679'
Plug #7 - 150 ex Class "C" cement @ 679' to surface.
Pump 9.5# mud between cement plugs. Weld 1/2" steel plate on top of surface casing. Install 4" x 4" dry hole marker.
WELL PLUGGED AND ABANDONED 10-7-81

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

J.R. Hughes

TITLE

Dist. Drilling Supt.

DATE

12-11-81

APPROVED

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

DATE

NOV 30 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.