U ED STATESM 01 ovember 1983) ormerly 9–331) BUREAU OF LAND MANAGEMEN	(UM) verse side)	5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT—" for such p	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS X OTHER	RECEIVED BY	7. UNIT AGBEEMENT NAME
NAME OF OPERATOR		8. FARM OR LEASE NAME
Liberty Oil & Gas Corporation V	MAR 03 1986	Doris Federal
	0760 O. C. D.	1
LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.)	y State requirespan OFFICE	10. FIELD AND POOL, OR WILDCYT
At surface 1980' FSL & 1980' FEL		Burton Flat-Mörrow 11. shc., t., b., m., or alk. and survey or area
PERMIT NO. 15. ELEVATIONS (Show whether D	DF BT GR etc.)	Sec. 26, T2OS, R28E
3263.		Eddy N.M.
Check Appropriate Box To Indicate I		
NOTICE OF INTENTION TO :		QUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING CABING
SHOOT OR ACIDIZE     ABANDON*       REPAIR WELL     CHANGE PLANS	SHOOTING OR ACIDIZING ABANDONMENT <sup>®</sup>	
(Other) Perforate and Test Atoka XX DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertine	Completion or Recom	ts of multiple completion on Well pletion Report and Log form.)
Drill out C.I.B.P. @ 10,330'. Set C.I.B		existing Morrow perforation
<pre>11,163-11,330' and place 10' cement on t Run Isolation Packer to 10,740'(to isola Packer to 1000 psi. Perforate Atoka from 10,952-10,958, 11,0 production.</pre>	te Wolfcamp perfs 930.	
Verbal approval received from my Bob Pit	SCIRE 2/11/00.	
signed letty that the foregoing is tryg and correct	Agent	DATE 2/21/86
(This space for Federal or State office use) (uling		DATE 2.28.84
AFPROVED BY TITLE		DATE
*See Instruction	ns on Rev <b>erse Side</b>	

•