Form 3160-5 (JUNE 1990) DEPARTMENT OF THE INTERIOR N.M. Oil COM. LIVISION FORM APPROVED BURFALL OF LAND BUREAU OF LAND MANAGEMENT811 S. 1st 6

Budget Bureau No. 1004-0135

CIST

1-28	24 Expires:	March 31, 1993
5. Lea	se Designatio	March 31, 1993 on and Serial No.

6. If Indian, Allottee or Tribe Name

٦.	Dease Designation and Serial
	NM-17103

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

SUNDRY NOTICES AND REPORTS ON V

Use "APPLICATION FOR PERMIT-" for such proposals			
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation		
Type of Well			
Oil Gas			
Well Well Other	8. Well Name and No.		
Name of Operator	Lee Federal #3		
STRATA PRODUCTION COMPANY	9. API Well No.		
Address and Telephone No. P. O. Box 1030	30-015-24421		
Roswell, New Mexico 88202-1030 505-622-1127	10. Field and Pool, or Exploratory Area		
Location of Well (Footage, Sec., T., R., M., or Survey Description)	Wildcat Yates		
1975' FNL & 1765' FEL	11. County or Parish, State		
Section 25-20S-28E	Eddy County, New Mexico		

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

	TYPE OF SUBMISSION		TYP	E OF ACTION		
X	Notice of Intent	X	Abandonment			Change of Plans
			Recompletion			New Construction
	Subsequent Report		Plugging Back			Non-Routine Fracturing
			Casing Repair			Water Shut-Off
	Final Abandonment Notice		Altering Casing			Conversion to Injection
			OTHER			Dispose Water ort results of multiple completion on Well
					Completio	n or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Strata Production Company requests approval to plug and abandon the well within six months in the following manner:

- MIRU. PU and TIH with 2 3/8" tubing. Tag up at TD. Load hole with gelled water. 1. Set 35 sack cement plug at 1190'.
- Set 35 sack cement plug at 670' across 7" casing shoe. 2.
- Set 10' cement plug at surface. 3.
- Set Dry Hole marker. Clean and rip location and reseed



4. OSE BIJ FISIO MAINEM GIGANI	ARTESIA ES
14. I hereby certify that the foregoing is true and correct Signed And Lawren	Title Production Records Manager Date 4/05/99
(This space for Federal or State office use VID R. GLAS Approved by (ORIG. SGD.) DAVID R.	S Title PETROLEUM ENGINEER Date MAY 0 4 1888
Conditions of approval, if any:  Title 18 U.S.C. Section 1001, makes it a crime for any person knownery.	and will fair to make to any department or agency of the United States any false, fictitious or fraudulant statements or
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly representations as to any makes the arms of the company of the compan	See Instruction on Reverse Side F3160-5.WKI