ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION EIVED BY P. O. BOX 2088	rm C-103 ·		
	m C-101 .		
	vised 10-1-78		
Sa. Indicate Type of Le	ase		
	Foe		
OPENATOR I ARTESIA, OFFICE S. State OIL & Gas Lea	se No.		
K-6854			
SUNDRY NOTICES AND REPORTS ON WELLS 100 HOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
OIL X GAS 7. Unit Agreement Name			
, Name of Operator 8. Form or Lease Name			
Yates Petroleum Corporation 🗸 Stonewall	WM State		
Address of Operator 9. Well No.			
207 South 4th St., Artesia, NM 88210 4			
Location of Well 10. Field and Pool, or	Wildcat		
Und. Avalon De	laware		
UNIT LETTER FEET FROM THE LINE AND FEET FROM	7777777		
THE West LIVE, SECTION 30 TOWNSHIP 205 RANGE 28E NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.) 12. County Eddy	<u> </u>		
3285' GR Eddy	711111,		
^{b.} Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CA	51HG		
TEMPORABILY ABANDON PLUG AND ABA	NDONMENT		
PULL OR ALTER CASING			
OTHER			
0THER			

 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Killed well and pull tubing. Ran packer and RBP. Test RBP to 2000#, OK. COOH w/tubing and packer. WIH and perforated 2718-2727' w/8 .42" holes as follows: 2718, $18\frac{1}{2}$, 19, $19\frac{1}{2}$, 25, 26, $26\frac{1}{2}$ and 27'. GIH w/tubing and packer. Acidized perfs 2718-27' w/3000 gal 15% acid and 8 ball sealers. POOH w/tubing, packer and RBP. Reset RBP at 2615'. and tested to 2000#. WIH and perforated 2582-84 $\frac{1}{2}$ ' w/6 .42" holes as follows: 2582, $82\frac{1}{2}$, 83, $83\frac{1}{2}$, 84 and $84\frac{1}{2}$ '. WIH and perforated 2524-27 $\frac{1}{2}$ ' w/6 .42" holes as follows: 2524, $24\frac{1}{2}$, 25, 25 $\frac{1}{2}$, 27, 27 $\frac{1}{2}$ '. GIH w/ tubing and packer and acidized perfs 2582-84 $\frac{1}{2}$ ' w/2000 gal 15% acid and 6 ball sealers. Moved RBP to 2552' and packer to 2490'. Acidized perfs 2524-27 $\frac{1}{2}$ ' w/2000 gal 15% acid and 6 ball sealers. Move RBP to 2748' and test to 2000#, OK. COOH w/tubing and packer. Sand frac perforations (via tubing) w/40000 gal 75 Qualtiy Foam, 52000# (36000# 20/40 and 16000# 10/20) sand, 586,000 scf N₂ and 5000 gal methanol. Pull RBP out of hole.

8. Thereby certify that the information above is true and complet	te to the best of my knowledge and belief.		
un pranita Dodlett	Production Supervisor	DATE	11-18-83
	Original Signed By Leslie A. Clements	DATE	NOV 2 8 1983
CNDITIONS OF APPROVAL, IF ANY:	Supervisor District II		