of the hole, extending 4-foot above surface. Weld a steel plate to the top of the pipe. The steel plate should have the following inscription on it:

> EXXON CO., USA BURTON FLAT "C" FEDERAL NO. 3 SW SE, SECTION 35 PERMIT NO. 30-015-24695 T20S, R28E EDDY CO., NEW MEXICO DATE WELL PLUGGED

> > 1

6. Rig down, move out. Clean location.

PT app 11/13/87

Division Operations Superintendent

ENGR / SUPV ID

dw3.2proc BRTFLTC3.p&a

a.