

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input type="checkbox"/>
LAND OFFICE	<input type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

JUN -5 1987

O. C. D.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-9960	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Exxon Corporation Attn: David A. Murray		8. Farm or Lease Name Big Eddy State
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 99
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 2080 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 21S RANGE 28E NMPM.		10. Field and Pool, or Wildcat Fenton - Delaware
15. Elevation (Show whether DF, RT, GR, etc.) GR 3259.3		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-26-87 Spotted 50 sx CLC @ 3663'

5-27-87 Tag above plug @ 3065', load hole with saltwater gel, set CIBP @ 2875' and spotted 30 sx CLC on top of plug. Filled hole from 400' to suf. w/ cmt.

5-28-87 Cut off wellhead and weld on dry hole marker.

Post 20-2
6-12-87
P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David A. Murray TITLE Permits Supervisor DATE 6-4-87

APPROVED BY David Moore TITLE Geologist DATE 1/20/88

CONDITIONS OF APPROVAL, IF ANY: