

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a **different reservoir**.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Hondo Oil & Gas Company

3. Address and Telephone No.

P. O. Box 2208, Roswell, NM 88201

(505) 625-6732

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

3009' FNL & 660' FWL; Sec. 6-T21S-R27E

5. Lease Designation and Serial No.

NMNM-0501759

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Kurland "A" #1

9. API Well No.

300152484700S1

10. Field and Pool, or Exploratory Area

Avalon Bone Springs

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Recomplete to Delaware

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- (1.) MIRU PU. POH w/ rods & pump.
- (2.) POH w/ tbg.
- (3.) Set CIBP @ + 4550' w/ 35' cmt. on top.
- (4.) Run GR-CBL-VDL from 3000' to 200' above TOC (est'd TOC @ + 2450').
- (5.) Perf. Delaware w/ 1 JSPF from 2692'-2706' (15 holes).
- (6.) Acidize w/ 1500 gals 7 1/2% acid.
- (7.) Swab & test.
- (8.) If oil productive frac.
- (9.) If non productive set CIBP @ 2785', perf Delaware @ 2652'-2666' (15 holes).
- (10.) Repeat steps (6.) - (8.).
- (11.) Run pump equip.

Our proposed date of starting is 10/30/91.

14. I hereby certify that the foregoing is true and correct

Signed E.L. Butters Jr.

Title Petroleum Engineer

Date 10/24/91

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date 10/28/91