

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on
reverse side)

Modified Form No.
NM60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

NM-15873

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Doris Federal

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

Burton Flat Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 26-20S-28E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Strata Production Company

3a. Area Code & Phone No.

505-622-1127

3. ADDRESS OF OPERATOR

P. O. Box 1030, Roswell, New Mexico 88202-1030

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surface

1980' FSL & 660' FEL

RECEIVED

O. C. D.
APTE

14. PERMIT NO.

30-015-24868

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3278' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion or well
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.) *

11/12/92 MI and RU Pride Well Service Rig #3.

11/13/92 TOH with rods, tubing and pump.

11/16/92 Perf (17) .42 holes from 5268' to 5318'.

11/17/92 Acidize with 1000 gal 7 1/2% NEFE with 30 BS. Swab test.

11/20/92 Frac via 2 7/8" tubing with 440 bbls 2% KCL, 35# X-link gel and 40000# 16/30 RC. Swab test.

11/23/92 TIH with 169 joints 2 7/8" tubing. Set SN at 5460'. Set TA at 5110'. Flange up and build wellhead. TIH with 2 1/2" x 1 1/2" x 16' pump, (2) 3/4" subs, (216) 3/4" rods, (1) 2' sub, (2) 6' sub and (1) 4' sub. Hung well on and spaced well out. Well placed back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Carol J. Garcia

TITLE Production Supervisor

DATE 12/17/92

(This space is for use by the Bureau of Land Management)

APPROVED BY

David A. Mass

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

CAN

6-1993

BLM, NEW MEXICO

*See Instructions on Reverse Side