Jubmit 3 Copies to Appropriate District Office	State of New Mexico Energy inerals and Natural Resources Department		Form C-103 Revised 1-1-89	
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240 <u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. <u>30-015-2494</u> 5. Indicate Type of Lease STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	0.	14 1992 . c. d.	6. State Oil & Gas Lease No. 483340	
( DO NOT USE THIS FORM FOR PAG DIFFERENT RESER (FORM C	CES AND REPORTS ON WELLS posals to drill or to deepen or avoir. Use "Application for PERMIT 101) FOR SUCH PROPOSALS.)	Log Bron 10 /	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL WELL X	OTHER		McCord "A"	
2. Name of Operator			8. Well No.	
Marathon Oil Compan 3. Address of Operator	y <u> </u>		9. Pool name or Wildcat	
•	bs, NM 88241		Burton Flat (Morrow North)	
4. Well Location				
Unit Letter P :66	Event From The South	Line and 560		
Section 19	Township 21-S Range	27-E N	VMPM Eddy County	
Section 1) Tomstip 22 B. Section 1) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3147' GL & 3168' KB				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:	
		EMEDIAL WORK		
	CHANGE PLANS	OMMENCE DRILLING		
	c	ASING TEST AND CE		
OTHER:	0	DTHER:		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon Oil Company proposes to acidize the existing perfs in the McCord "A" Well No.1. The Morrow perfs from 11460-478' will be acidized w/2000 gals of 7-1/2% NEFE HCL acid and 2000 gals of CO2. This work is scheduled to commence on October 14, 1992. Listed below is the proposed procedure and a wellbore sketch is attached:

- Shut well in. RU wellhead isolation tool. 1.
- 2. RU service company.
- 3. Acidize Morrow perfs 11,460-478' w/2000 gals of 7-1/2% NEFE HCL and 2000 gals of CO2.

2

- 4. Shut well in. RD wellhead isolation tool.
- 5. Open well to frac tank and recover load.
- Turn well to sales after CO2 concentration drops below contract levels. 6.

I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	ge and belief. Production Engineer	date10/12/92
TYPE OR PRINT NAME Kick Gaddis		TELEPHONE NO. 505/393-7106
(This space for State Use) ORIGINAL SIGNED BY		OCT 2 2 1992
APPROVED BY SUPERVISION DISTRICT		DATE
CONDITIONS OF APPROVAL, IF ANY:		