

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION

D r er DD

Artesia, NM 88210

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill, or to deepen or reentry to a different reservoir.

Use 'APPLICATION FOR PERMIT--' for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

1. Type of Well



Oil Well



Gas Well



Other

2. Name of Operator

Presidio Oil Company

Christine Pickart

Phone: (303) 850-1824

JUN 20 1994

3. Address and Telephone No.

5613 DTC Parkway, Ste 750, P.O. Box 6525, Englewood, CO 80155-6525

O. C. D.  
DISTRICT OFFICE

4. Location of Well (Footage, T, R, M, or Survey Description)

1980' FSL & 1980' FWL, Lot 19  
Section 1-T21S-R27E

5. Lease Designation and Serial No.

NM 40256

6. If Indian, Allottee or Tribe Name

-----

7. If Unit or CA, Agreement Designation

8. Well Name and No.

H.W. Stott Federal No. 1

9. API Well No.

30-015-25137

10. Field and Pool, or Exploratory Area

Avalon Bone Springs East

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION



Notice of Intent



Subsequent Report



Final Abandonment Notice



Abandonment



Recompletion



Plugging Back



Casing Repair



Altering Casing



Other:



Change of Plans



New Construction



Non-Routine Fracturing



Water Shut-Off



Conversion to Injection



Dispose Water

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.

If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)\*

Proposed work: It is believed this well is perforated 'off depth'. Presidio will attempt to squeeze off existing perms, reperfurate from 3035'-3060'. All squeeze holes will be tested to 1000# before proceeding to the next step.

Move in and rig up.

Lay down rod string

Nipple up BOP

Strap out of hole w/ tbg

RIH w/pkr to 2650'± and squeeze off perforations from 2750'-2765'

Drill out squeeze

Perforate Delaware formation from 3035'-3060' w/8 SPF

RIH w/pkr to 3015'±, swab test well

Frac perforations via tbg

POOH w/pkr, install necessary production equipment

Rig down and move off location.

14. I hereby certify that the foregoing is true and correct

Signed:

Jerry Holder

Title: Area Foreman

Date: June 7, 1994

(This space is for the signature of the Approving Authority)

(ORIG. SGD.) JOE G. LARA

Title:

PETROLEUM ENGINEER

Approved by:

Date:

6/14/94

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\* See Instructions on Reverse Side