

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN  
(Other than  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-27801

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tuesday A Federal

9. WELL NO.

No. 1

10. FIELD AND POOL OR WILDCAT  
V.N.P. Bone Springs  
Southpark Wolfcamp

11. SEC., T., R., OR BLM AND  
SURVEY OR AREA

3-20S-29E

12. COUNTY OR PARISH 13. STATE

Eddy NM

OCT 20 '87  
SUNDRY NOTICES AND REPORTS ON WELLS  
Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Conoco Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1400' FNL & 990' FWL - Unit Letter E

14. PERMIT NO.

30-015-25511

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3334' GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Correction to Sundry Notice Report of July 29, 1987 approved by BLM on August 7, 1987.

MIRU gympole and slickline, install 5000 psi lubricator on Swab valve. Release Hg at the Baker on-off tool. Allow equalization of Hg & backside, annulus is presently loaded with skt fluid. Strap out of hole w/ 2 7/8" Hg. Fill csq to surface with 75 BTFW & pressure test csq to 1000 psi surface pressure for 10 mins. GIH w/ spring gauge on junk basket and wireline to 9100'. POOH. Log from 9000'-3230'. POOH. GIH w/ 7" RBP. Set at 6000'. Test to 1000 psi surface pressure. Conduct pressure buildup surveys if necessary. Acidize Bonesprings w/ 2520 gals 7 1/2% HCL-NE-FE acid inhibited for 24 hrs at 115° F. Acidize in three stages w/ 840 gals acid. Quert w/ 100 lbs-graded

18. I hereby certify that the foregoing is true and correct

SIGNED John H. Harty, Jr. TITLE Administrative Supervisor

DATE October 5, 1987

(This space for Bureau or State office use)

APPROVAL OF  
COMMISSIONER OF APPROVAL, IF ANY:

TITLE

DATE 10-14-87

\*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlbad (6) File