

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Alameda, NM 88210

SUBMIT IN TRIPlicate
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 38627

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gobbler's Knob 30 Fed. Com.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Happy Valley /Morrow/

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T22S, R26E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry-Hole

2. NAME OF OPERATOR
HNG OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 2267, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2180' FSL & 1980' FWL, Section 30

14. PERMIT NO.

Cer #360

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3463.2' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all marker pertinent to this work.)

10-13-86 - TIH to 10,800'; set 100 Sx plug 10,800 to 10,600 feet.

10-14-86 - Set 200 sx plug 10,300 to 9800 feet.
Set 100 sx plug 8550 to 8350 feet.
Set 60 sx plug 6000 to 5850 feet.
Set 60 sx plug 4950 to 4800 feet.
Set 60 sx plug 3400 to 3250
Set 60 sx plug 2650 to 2500 feet.
Set 40 sx plug 1700 to 1600 feet.
Set 20 sx plug 40 feet to surface.

Cut off WH & Cap well. Rig Released 11:00 pm 10-14-86

18. I hereby certify that the foregoing is true and correct

SIGNED

Betty Gildon

TITLE Regulatory Analyst

DATE 10/17/86

(This space for Federal or State office use)

APPROVED BY

Don C. Adams

TITLE

DATE 7-24-87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post ID-2
10-31-86
p & A