

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
verse side)

TE
re

Budget Bureau No. 1004- C-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-57602

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 15

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Revelation Bone Spring

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 15, T-22-S, R-25-E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

SEP 27 1991

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

INDREX, Inc.

3. ADDRESS OF OPERATOR

7633 E. 63rd Place, Suite 500, Tulsa, Oklahoma 74133

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

2080' from North line and 1980' From East Line

14. PERMIT NO.

NM-57602

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3502 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANT

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

On 5-3-89 notified BLM & got verbal approval to plug & abandon well as follows:

1. Pulled rods and found 2-3/8" tbg stuck @ tbg anchor @ 4305'.
2. Cut tbg @ 4290' & pulled.
3. Set 5-1/2" CIBP on WL @ 4288'.
4. Displace hole w/100 bbl 10.0 ppg mud.
5. Spot 5 sx Cl H cmt plug 4288'-4246'.
6. Cut 5-1/2" csg @ 2086' then pull & LD 48 jts csg.
7. RLH w/2-3/8" tbg & spot 30 sx Cl H cmt plug 2136'-2016'.
8. WOC 12 hrs & tag cmt plug @ 1950'.
9. Spot 30 sx Cl H cmt plug 600'-500'.
10. Spot 15 sx Cl H cmt plug 60' to surf
11. Cut off wellheads 3' BGL & install dry hole marker 5-8-89.

SEP 25 11 06 AM '91
CABLE AREA HEADQUARTERS

RECEIVED

Approved by _____
License No. _____
Service restoration is completed.

Post ID-2
10-11-91
PVA

18. I hereby certify that the foregoing is true and correct

SIGNED

Shannon J. Shaw

TITLE Agent for INDREX, Inc.

DATE 9-23-91

(This space for Federal or State office use)

Orig Signed by Shannon J. Shaw

PETROLEUM ENGINEER

APPROVED BY

TITLE

DATE 9/26/91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side