

RECEIVED

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION TOP BOTTOM

DESCRIPTION OF ZONES, ETC.

CARBONATE ZONE
AREA: ...

38.

GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Yates	1463	1463
Delaware	3414	3414
Bone Springs	6170	6152
3rd Bone Spr. Sd	9234	9081
Wolfcamp	9822	9653
Strawn	10852	10647
Atoka	11225	10998