Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I

OIL CONSERVATION DEVISION

Indicate Type of Lease	·····································
ELL API NO. 30-015-26048	

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 208	8	WELL API NO.		
DISTRICT II	Santa Fe, New Mexico		30-015-2	6048	
P.O. Drawer DD, Artesia, NM 88210	Sama I C, I CON INICATOR	MAY - 1 89	5. Indicate Type of L	STATE XX FEE	\neg
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		O. C. D.	6. State Oil & Gas Le		_
SUNDRY NOTICE	S AND REPORTS ON WEL	LS			
(De Mer Bot Miles Of Miles Of Miles	CALC TO CHILL OIL TO DEEL CIT	0,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7. Lease Name or Un	it Agreement Name	
	NR. USE "APPLICATION FOR PEF I) FOR SUCH PROPOSALS.)	IMI I	Dinero Ex	xon 22 State	# 1
. Type of Well:	<u> </u>		7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		" -
OIL GAS WELL STATE OF THE CONTROL OF	OTHER				
Name of Operator			8. Well No.		
Dinero Operating Comp	any /		1		
. Address of Operator			9. Pool name or Wild		
P.O. Box 10505, Midla Well Location	nd. Texas 79702		Catclaw Dr	aw (Delaware)	
	Feet From The North	,	0 5 5 73	East	Line
Unit Letter : : :	Feet From the	Line and	rea From 1		Line
Section 2.2	Township 21-S Ran	ige 25-E	NMPM Edd	Y Count	y
	10. Elevation (Show whether I		P		
	3,444.	3 G.L			
1. Check Ap	propriate Box to Indicate N	Nature of Notice, R	Leport, or Other D)ata	
NOTICE OF INTE	NTION TO:	SUE	SEQUENT RE	PORT OF:	
TREADU MONE	51110 4110 45441504	DEMEDIAL MODIC		TERMO CACINO	
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	AL	TERING CASING	
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	GOPNS. 📙 PL	LUG AND ABANDONMEN	T []
JLL OR ALTER CASING		CASING TEST AND C	EMENT JOB		
THER:		OTHER: Ir	stall Pumpi	na Unit	$\overline{X}X$
		OTHER.			
Describe Proposed or Completed Operations work) SEE RULE 1103.	i (Clearly state all pertinent details, an	d give pertinent dates, incli	iding estimated date of st	arting any proposed	
•		66 11	5 2 11	1411 16418	
04-21-89 Rig up pull	ing unit. Bleed	gas off well	. Ran Z"XII	./4"X16X\"	
traveling bbl. pump i cemove some weights t	n hole with 100 /	/8 steel roo	is. Hang we	01,	
remove some weights t	o barance out.	mue down une	.II Monday,	04 24 0).	
04-24-89 Wait on Med	hanic.				
		-+ 24741			
)4-25-89 Start well	to pumping, pump	at 24/4'			
04-26-89 Start test					
74 20 O) Start test					
04-27-89 40 oil, 55	water, 59 MCFPD				
, 2	•				
hereby certify that the information above is true and	complete to the best of my knowledge and	belief.			
(Klima Kl	I Dolfin		ion Clerk	DATE _4/28/89	
SIGNATURE	т	<u> rrounct</u>	CON CICIA	_ DATE _ + / 20/-02	
TYPEORPRINTNAME Dana Ral	ston			телерноме но. (915)	684-
This same for Sect. U.S.					****
(This space for State Use) Origina	al Signed By			MAY 1	1989
14.4				- LT h	

Mike Williams

.

_ DATE -

CONDITIONS OF APPROVAL, IF ANY: