Form 3160-5 (June 1990)	UNITED STA DEPARTMENT OF TH BUREAU OF LAND MA	E INTERIOR	Drawer DD	COMMISSION FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 88219 Lease Designation and Serial No.			
S Do not use this form Use	0 ir. NM 81217 6. If Indian. Allottee or Tribe Name						
	7. If Unit or CA, Agreement Designation						
Type of Well Gas Well Gas Well Gas Santa Fe Ene: Address and Telephone No.	8. Well Name and No. BAND AID FEDERAL 9. API Well No.						
550 W. Texas 4 Location of Well (Footage, So 2063' FWL & 129	10. Field and Pool, or Exploratory Area INDIAN BASIN 11. County or Parish, State						
			UT. C	EDDY CO., N.M.			
TYPE OF SUE	PROPRIATE BOX(s) TO INI	DICATE NATUR	E OF NOTICE, RE	PORT, OR OTHER DATA			
			TYPE OF ACTI	ON			
X Notice of Inte Subsequent R Final Abando	гроп	Abandonment Recompletion Plugging Back Casing Repair Altering Casin X Other Con	s vert to WSW.	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report result of multiple completion on Wetl			
13. Describe Proposed or Completed Operations (Clearly state all participant deails and size and log form.)							
The subject wel (Steve Sell). for water suppl above the exist hole section an	l was temporarily abar Santa Fe Energy Operat y well purposes. Sant ing perforations, pu	ndoned in Nov ting Partners ta Fe will P& Lling 7" prod asing shoe.	ember of 1989, , L.P., vill ut A the lower wel uction casing, The 9-5/8" casi	by the previous operator ilize the upper well bore i bore by setting a plug setting a plug in the open ng will be logged and			

OISF

The above work is to begin on or before February 20, 1995. SUBJECT TO LIKE APPROVAL BY STATE		、注意に必要で

Signed	Sr. Production Clerk	Date21/94
(This space for Federal or State office use) Approved bySigned by Shannon J. Shew Conditions of approval, if any:	Tit. PETROLEUM ENGINEER	12/13/94

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MIDLAND CENTRAL DIVISION CONDITION OF HOLE & PROCEDURE

SANTA FE ENERGY RESOURCES, INC.

DATE: November 15, 1994

FIELD:	Indian Basin	LOCATION:	1294' FNL & 2063' FWL
LSE/UNIT:	Band Aid Federal		Sec. 5, T-22-S, R-24-E Eddy County, New Mexico

WELL NO. 1

OBJECTIVE: To cut and pull 7" production casing, plug & abandon the lower wellbore below the 9-%" intermediate casing, and test for shallow water zones.

CONDITION OF HOLE:

ETD or TOTAL DEPTH: 7718' PBTD: 7695' K.B. DATUM IS 4225' G.L. DATUM IS 4210'

- CASING RECORD: •13-% " @ 369' w/900 cmt. (circ'd) •9-¾" @ 2500' w/811 cmt. (Pumped 711 sx Cl. "C" + 100 sx Cl. "C" cap at surface) •7" @ 7689' w/250 sx cmt. (TOC @ 7390' by CBL) •4-½" liner @ 7154'-7714' set w/50 Cl. "H" sx cement.
- **PERFORATIONS:** 7683'-88' (open)
- TUBING DETAIL: Last report 10/31/89, 2-4 6.5#, J-55 tbg, Baker Model "R" Double Grip Pkr, and Submergible pump set @ 7100'.

ROD & PUMP DETAIL:

REGULATORY AGENCY REQUIREMENTS: G-103, Sundry Notices, Federal Form 3160-5 to BLM.

PROCEDURE:

● CAUTION: THIS WELL IS CURRENTLY PRESSURED UP WITH SOUR GAS (H₂S CONCENTRATIONS ABOVE 3,500 PPM). WORK WITH EXTREME CAUTION WHEN PLUG AND ABANDONING THE LOWER WELL BORE.

NOTE: All cement to be Class "C" w/2% CaCl.

- If necessary kill well w/9 PPG mud. 1.
- 2. MIRU PU. ND WH & NU BOP.
- Release packer and POH w/tbg and submergible pump. 3.
- RU wireline unit, RIH w/gauge ring and set EZSV retainer @ $\pm7100'$. 4.
- 5. RIH w/tbg and sting into retainer.

Band Aid Federal No,. 1 - Recompletion Continued

- 6. Mix and pump 150 sx Class "C" cement. Sting out of retainer and pump 50' cement plug on top of retainer. POH w/tbg.
- Run free-point on 7" production casing. Cut 7" casing @ ±7000' or at free-point and POH laying down 7" casing. Note depth of 7" casing stub.
- RIH w/open ended tbg and tag cement plug inside 7" casing. Load hole w/9 PPG mud.
- 9. PUH to 75' below top of 7" casing stub or pump cement from top of cement plug if 7" casing is cut @ 7000'. Pump 150' Class "C" cement plug to a minimum 75' above 7" casing stub. PUH, WAIT ON CEMENT AND TAG PLUG.
- 10. PUH and set a minimum 100' cement plug in open hole midway between 9-%; casing shoe and 7" casing stub (≈4750'-4850' if 7" casing cut @ 7000'). PUH, WAIT ON CEMENT AND TAG PLUG.
- 11. PUH to 2575' and pump 150' Class "C" cement plug across 9-% casing shoe (2575'-2425'). PUH, WAIT ON CEMENT AND TAG PLUG.
- 12. Circulate 9-%" casing with clean brine water (casing needs to be loaded with brine water for logging purposes) and POH to run logs.
- 13. RU Schlumberger Logging Services, run Thermal Time Decay (TDT) log from PBTD to base of 13-% surface casing @ 369'. RD logging company & shut down for logging evaluation.
- 14. RU wireline company and perforate potential fresh water zones per Schlumberger TDT log and Schlumberger - Compensated Neutron/Litho Density log (dtd. 08/13/89).
- 15. Swab test well to evaluate water zone and pumping equipment design.
- 16. RU wireline company and perforate potential fresh water zones per Schlumberger Thermal Decay Temperature (TDT) log and Schlumberger -Compensated Neutron/Litho Density log (dtd. 08/13/89).
- 17. RIH w/rental ESP on 2-7/8" production tubing to below perforations. Utilize generator and pump water to rental tanks. Evaluate well to determine if a sufficient volume of water can be produced to support the needs of SFER drilling department .
- NOTE: P&A of the lower wellbore was coordinated with Joe Laura, Bureau of Land Management per telephone conversation/fax on 11/09/94.
- NOTE: Conversion of well to Water Source Well has been coordinated with Ken Fresquey, New Mexico State Engineer - Roswell, New Mexico per telephone conversation on 11/21/94.



