3-27-90: Tag cmt. at 1060'. Set plug No. 7 w/ 200 sx C1. "C" + 2% CaCl. WOC. Tag cmt. at 820'. Set plug No. 8 w/ 200 sx C1. "C" + 2% CaCl. WOC. Tag cmt. at 634'. Set plug No. 9 w/ 200 sx C1. "C" + 2% CaCl. WOC. Set plug No. 10 w/ 182 sx C1. "C" + 2% CaCl. Circulated 15 sx good cmt. to surface. WOC 16 hours.

3-28-90: Pressure test casing to 1500 psi - okay. Resume drilling operations.

.

-