

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

T
C/SF
✓Open

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
811 S. FIRST ST.

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-015-26280
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name LONE TREE FEDERAL COM
8. Well No. 1
9. Pool name or Wildcat EAST CARLSBAD (BONE SPRINGS)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator COLLINS & WARE, INC.
3. Address of Operator 508 W. WALL, STE. 1200 MIDLAND, TX 79701	4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>2120</u> Feet From The <u>WEST</u> Line Section <u>24</u> Township <u>21S</u> Range <u>27E</u> NMPM <u>EEDY</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3126' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-15-98 THRU 12-28-98

MIRU PU. SET CIBP @6575'. CIRC HOLE W/10 PPG MUD.
SPOT 25 SX CMT ON TOP OF CIBP.
CUT 5½" CSG OFF @4505' & POH.
SPOT 50 SX CMT PLUG @5438'. SPOT 50 SX CMT PLUG @4573'.
TAG CMT PLUG @4727'. SPOT 50 SX CMT PLUG @4573'.
TAG CMT PLUG @4439'. SPOT 35 SX CMT PLUG @2357'.
TAG CMT PLUG @2293'. SPOT 35 SX CMT PLUG @2293'.
TAG CMT PLUG @2103'. SPOT 35 SX CMT PLUG @711'. TAG CMT PLUG @586'.
SPOT 10 SX CMT SURF PLUG. CUT OFF WELLHEAD & WELD ON CAP.
INSTALL P&A MARKER. COVER PIT & CELLAR. WELL P&A 12-28-98.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Chiles TITLE ENGR. TECH DATE 01-11-99

TYPE OR PRINT NAME DAVID CHILES TELEPHONE NO. (915) 687-3435

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 3-23-99

CONDITIONS OF APPROVAL, IF ANY:

