

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION  
Drawer DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

DEC 17 1993

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
**EXXON CORPORATION ATTN: REGULATORY AFFAIRS**

3. Address and Telephone No.  
**P. O. BOX 1600 MIDLAND, TX 79702 (915) 688-6748**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
**1305' FNL AND 1305' FEL, SEC.31-20S-28E**

5. Lease Designation and Serial No.

**NM-01119**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.  
**YATES C FEDERAL 36**

9. API Well No.  
**3001526370**

10. Field and Pool, or Exploratory Area  
**AVALON DELAWARE**

11. County or Parish, State

**EDDY NM**

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION


- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection

**SPILL REPORT**

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

ON NOVEMBER 18, 1993 20 BARRELS OF OIL AND 10 BARRELS OF WATER WERE SPILLED AT THE ABOVE REFERENCED LOCATION. THE SPILL OCCURRED WHEN WELL WAS SWITCHED OUT OF TEST HEADER AND FAILED TO OPEN PRODUCTION HEADER. IN EFFECT WELL PUMPED AGAINST CLOSED LINE BUILDING PRESSURE UNTIL STUFFING BOX PACKING FAILED. SHUT DOWN PUMPING UNIT AND REPACKED STUFFING BOX. APPROXIMATELY 22 BARRELS OF FLUID WERE RECOVERED. A VACUUM TRUCK WAS USED TO PICK UP FREE FLUID, AFFECTED AREA WAS WASHED, FERTILIZED AND TILLED FOR REMEDIATION.



RECEIVED  
DEC 8 10 24 AM '93  
OIL  
ARTESIA

14. I hereby certify that the foregoing is true and correct

Signed Sally R. Urby

Title Sally R. Urby  
Staff Office Assistant

Date 12/06/93

(This space for Federal or State office use)

Approved by \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

Conditions of approval, if any: