-Electric Logs: Dual Induction Laterolog Neutron Porosity Log Gamma Ray/Caliper Log

-Coring: Some sidewall coring will be done if necessary.

- 9. Abnormal Pressures, Temperatures, or other Hazards: -Lost circulation is anticipated in the surface interval of the hole, and possibly in the Capitan Reef interval.

2