

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-26584
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-1673

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Lost Tank AIS State
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	8. Well No. 1
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210	9. Pool name or Wildcat Lost Tank Delaware
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>21S</u> Range <u>31E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3612' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Perforate, Treat</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-4-92. Drilled out DV tools at 4592' and 7426'. Perforated zone 1 - 8382-8406' w/16 .50" holes (2 SPF) as follows: 8382, 83, 90, 91, 98, 99, 8405, 8406' Acidized 8382-8406 w/750 g. 7½ NEFE acid. Frac'd zone with 2000g. 35# linear gel, 9500g. 35# XL gel w/24000 20/40 sand. Perforated zone 2 - 7148-7208' w/24 .50" holes (2 SPF) as follows: 7148, 50, 55, 60, 64, 67, 70, 95, 99, 7203, 06 and 7208'. Acidized 7148-7208' w/1000 g. 7½ NEFE acid. Frac'd zone with 3000g. 35# linear gel, 19000 g. 35# XL gel w/46000# 16/30 sand.
1-10-92. Set pumping equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-27-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY

WILLIAM

DISTRICT II

APPROVED BY _____ TITLE _____ DATE JAN 29 1992

CONDITIONS OF APPROVAL, IF ANY: