

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26586
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1673
7. Lease Name or Unit Agreement Name Lost Tank AIS State
8. Well No. 3
9. Pool name or Wildcat Lost Tank Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER WORKOVER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION ✓

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line
Section 36 Township 21S Range 31E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-2-91. Drilled out CIBP @ 8270', drilled to 8520'. Circulate 1 hour with no cuttings.
10-3-91 Perforated 8476, 79, 83, 87, 90 (10 holes-2 SPF); perforated 8062, 65, 68, 70, 75 (10 holes-2 SPF); perforated 6654, 56, 60, 64, 65, 68, 88, 90, 92, 94 (20 holes-2 SPF). Acidized perfs 8476-90' w/750g. 15% NEFE acid. Straddle existing perfs 8288-90'. Frac'd w/ 1500g. 35# linear pad, 5100g. 35# XL gel with 11800# 20/40 sand. Straddle perfs 8062-75'. Acidize w/750g. 7½% NEFE acid. Frac'd perfs 8062-75' w/3000g. 35# linear pad, 10000g. 35# XL gel w/22500# 20/40 sand. Acidized perfs 6654-94' w/1500g. 7½% NEFE acid. Frac'd w/3000 g. 35# linear gel, 10000 g. 35# XL gel w/22500# 20/40 sand. Perforated 6553', 56, 57, 58, 59 (10 holes-2 SPF). Acidized w/750g. 7½% NEFE acid. Frac perfs 6553-59' w/3000g. 35# linear gel, 10000g. 35# XL gel w/22500# 20/40 sand.

10-12-91. Ran new rods and returned well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 10-14-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE OCT 18 1991

CONDITIONS OF APPROVAL, IF ANY: