UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	I APPRO	OVED
Budget Bure	eau No.	1004-013
Expires:	March	31, 1993

				_		<u>, </u>	_		
5.	Lease	Designation	and	S	e	ri	ai	١	lo

NM	04	ጸ	2	5
TATT	$^{-}$	v	_	J

		<i>C</i>			
(June 1990) DEPARTMEN BUREAU OF I SUNDRY NOTICES Do not use this form for proposals to dri	TED STATES T OF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELLS Ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM 04825 6. If Indian, Allottee or Tribe Name			
	IN TRIPLICATE	7. If Unit or CA, Agreement Designation			
1. Type of Well Oil XX Well Other 2. Name of Operator YATES PETROLEUM CORPORATION 3. Address and Telephone No. 105 South 4th St., Artesia, I		8. Well Name and No. Trigg AIN Federal #1 9. API Well No. 30-015-26697 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey D. Unit H, 1980' FNL & 660' FEL, S.	Sec. 28-T20S-R29E	East Burton Flat Strawn 11. County or Parish, State Eddy, NM			
	s) TO INDICATE NATURE OF NOTICE, REPO				
TYPE OF SUBMISSION XX Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other Add additional Strawn pay.	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Well was recompleted in Strawn perforations 10582-10611, 6-21-92. Propose to add remaining Strawn intervals as follows: 1) RU lubricator and perforate Strawn Lime 10763-10771' (10 holes). Test prior to acidizing. 2) Straddle Strawn interval 10763-10771' and acidize w/1500 gals 15% NEFE/HCL acid. 3) Put on line and test. 4) If decision is made to continue with procedure, RU lubricator and perforate Strawn Lime 10680-10687' (10 holes). 5) Straddle Strawn 10680-10687' and acidize w/1500 gals 15% NEFE/HCL acid. 6) Straddle entire Strawn zone and swab test. 					
14. I hereby certify that the foregoing is thue and correct Signed (and a) and the	Title Production Supervisor	Date3-31-93			
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Tide <u>D. 1924 D. M. ENGINEER</u>	Date 4 (25/93			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.