## CRA BLM FORMAT

## APPLICATION FOR SURFACE COMMINGLING, OFF LEASE STORAGE AND MEASUREMENT APPROVAL

## This Format Should Be Attached To A Sundry Notice

To: Bureau of Land Management P. O. Box 1778 Carlsbad, New Mexico 88221-1778						
gurface co	mminalina .	and off	-lease	storage	uesting approval for and measurement of mation(s) and well(s Name: Burton Flat "7"	ρf
Well No.	Loc.	Sec.	Twp.	Rng.	<u>Formation</u>	
1_	<u> </u>		<u> 20S</u>	28E	Morrow	
with hydrod well(s) on	carbon prod Federal lea	uction ise No.	from the NM-8358	e follow 4 ; Le	ing formation(s) and ease Name: Federal "V	d /"
Well No.	Loc.	Sec.	Twp.	Rng.	Formation	
_1	G	8	<u>20</u> S	28F	Morrow_	
Production				s as foll		
Burton Federa	Iame and No. Flat "7" Fed	. #1 <u>N</u>	_	N/A N/A		

Continued ...

<sup>\*</sup> only gas will be comingled off lease