

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AN 3 0 1992

O. C. D.
ARTESIA OFFICE

WELL API NO. 30-015-26760
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG 9280
7. Lease Name or Unit Agreement Name Mary AIV State
8. Well No. 5
9. Pool name or Wildcat Lost Tank Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3643' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line Section 36 Township 21S Range 31E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3643' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8565'. Reached TD 1-3-92. Ran 195 joints 5-1/2" 17# and 15.5# J-55 casing set 8557'. Float shoe set 8557', float collar set 8513'. DV tools set 4532' and 7370'. Cmt'd in 3 stages. Stage 1: 225 sx "H", 8#/sx CSE, .6% CF-14, 5#/sx Gilsonite, .35% Thrifty Lite (yield 1.75, wt 13.6). PD 4:47 1-5-92 with 800 psi. Circulate thru DV tool 3 hrs. Circulate 125 sacks. Stage 2: 600 sx "H", 8#/sx CSE, .5% CF-14, 8#/sx Gilsonite, .35% Thrifty Lite (yield 1.82, wt 13.4). PD 8:55 PM 1-5-92 with 1250 psi. Circulate thru DV tool 3 hrs. Circulate 99 sacks. Stage 3: 425 sx Super "C" (yield 2.25, wt 11.5). Tailed in w/200 sx "C". Neat (yield 1.32, wt 14.8). PD 12:49 AM 1-6-92 with 1500 psi. Circulate 42 sacks. WOCU 4 days.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 1-27-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-147

(This space for State Use)
ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE FEB 17 1992

CONDITIONS OF APPROVAL, IF ANY: