

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26794
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1673
7. Lease Name or Unit Agreement Name Lost Tank AIS State
8. Well No. 8
9. Pool name or Wildcat Lost Tank Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>21S</u> Range <u>31E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3591' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8530'. Reached TD 10-19-91. Ran 197 joints 5-1/2" 15.5# and 17# J-55 casing set 8530'. Float shoe set 8530', float collar set 8485'. DV tool set 7435 and 4750'. Cemented in three stages as follows: Stage I - 500 g. mudflush ahead, 500 g. Surebond, 200 sx Class "H" + 8#/sx CSE + .6% CF-14 + 5#/sx Gilsonite + .35% Thrifty Lite (yield 1.74, wt 13.6). PD 6:45 AM, 10-20-91. Circ 15 sacks. Circ thru DV tool 2 hrs. Stage II - 500 g. mudflush ahead, 500 g. Surebond, 600 sx Class "H" + 8#/sx CSE + .5% CF-14 + 10#/sx Gilsonite + .35 Thrifty Lite (yield 1.82, wt 13.4). PD 9:45 AM 10-20-91. Circ thru DV tool 4 hrs. Circ 125 sacks. Stage III - 450 sx Super "C" (47# Class "C" + 20# Poz A + 17# CSE) (yield 2.25, wt 11.5). Tailed in 150 sx Calss "C" Neat (yield 1.32, wt 14.8). PD 3:45 PM 10-20-91. Circ 95 sacks. Notified Johnny Robinson, NMOCD, Artesia, NM, to witness - did not witness. WOC 18 hrs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 10-22-91

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV - 6 1991