		2. So the second sec		ONSERVATION DIV
			LC	ONSERVATION DIV 1st ST. ESIA, NM 88210-2834
			811 5	ESIA, NM 88210-200
rm 3160-5 ine 1990)		ED STATES '	Activ	FORM APPROVED
aic (770)	DEPARTMENT OF THE INTERIOR			Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LA	AND MANAGEMENT		5. Lease Designation and Serial No.
SU	JNDRY NOTICES A	ND REPORTS ON WELLS	1	NM-0554771
Jo not use this form	for proposals to drill	or to deepen or reentry tor PERMIT—" for such proposi		6. If Indian, Allottee or Tribe Name
Type of Well		N TRIPLICATE	JUL 1 1 1996	7. If Unit or CA, Agreement Designation
Vil Gas Cas Well	Other			
Name of Operator				B. Well Name and No.
J. C. Williams	son	ý		9 API Well No.
Address and Telephone No.				30-015-70587-95
C./O. P.O. Bo	OX 888 Hobbs, N c., T., R., M., or Survey Descr	M 88241-0888 505-39	2-7050	10. Field and Pool, or Exploratory Area
990' FSL & 216		ription)		🌾 Burton Flat Delaware
Sec. 16-T20S-I	R29E			11. County or Parish, State
				Eddy County, New Mexico
CHECK APP	ROPRIATE BOX(s)	TO INDICATE NATURE O	F NOTICE BEPOR	T OP OTHER DATA
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR			I, ON OTHER DATA	
Image: Solution         Type of Action           Image: Notice of Intent         Image: Solution of Intent				
	•	Abandonment		Change of Plans
Subsequent Rep	port	Plugging Back		New Construction
<b>L</b> J		Casing Repair		Non-Routine Fracturing Water Shut-Off
LJ Final Abandon	ment Notice	Altering Casing		Conversion to Injection
		X Other Runni	ing 4 1/2" casing	B Dispose Water
Describe Proposed on Complete	10			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe rippided of Completer	d Unerations (I learly state all per	tipent details and also marks and the		
		I Delite Pertineix		ny proposed work. If well is directionally drilled,
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to r	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at 1	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96.	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" hd joints, 5911' Cement with 1 "C" Modified Plug down at Carlsbad noti:	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96. fied of running	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" ho joints, 5911' Cement with 1 "C" Modified Plug down at Carlsbad noti:	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96. fied of running	5 1/4" bit at 7:30 PM 3-3-96. Run electric J-55, 8rd & buttress 4/sx celloflake. (yld 5 FL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM 3-5-96. BLM
Drill out of TD 6 1/4" hd joints, 5911' Cement with 1 "C" Modified Plug down at Carlsbad noti: Carlsbad noti: hereby certify that the foregoin Signed This space for Pederal or State Approved by	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96. fied of running	Agent	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Yld-1.48 @ 13.5#/gal. ed @ 7:00 PM.3-5-96. BLM
Drill out of TD 6 1/4" hd joints, 5911' Cement with 1 "C" Modified Plug down at Carlsbad noti: Carlsbad noti:	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96. fied of running	<pre>b 1/4" bit at 7:30 PM b-3-96. Run electric J-55, 8rd &amp; buttress f/sx celloflake. (yld fFL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"AgentAgent</pre>	on 2-22-96. Dr: logs to toal dep thread casing. 12.01 @ 12.4), 3#/sx Gilsonite bit. Rig release	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Y1d-1.48 @ 13.5#/gal. ed @ 7:00 PM.3-5-96. BLM
Drill out of TD 6 1/4" hd joints, 5911' Cement with 1 "C" Modified Plug down at Carlsbad noti: Carlsbad noti:	7" casing with 6 ole at 4:14 AM 3 , 4 1/2", 11.6#, 50 sx PSL + 1/4# + .3% FL-25 +.3% 3:00 PM 3-5-96. fied of running	<pre>b 1/4" bit at 7:30 PM b-3-96. Run electric J-55, 8rd &amp; buttress f/sx celloflake. (yld fFL-52 + 3#/sx salt + Circulate 28 sx to p and cementing 4 1/2"</pre>	on 2-22-96. Dr: logs to toal dep s thread casing. 12.01 @ 12.4), - 3#/sx Gilsonite oit. Rig release casing.	ny proposed work. If well is directionally drilled, ill 6 1/4" hole to 5905'. oth. Rig up and run 187 Set casing at 5905'. tailed with 400 sx. Super e. Y1d-1.48 @ 13.5#/gal. ed @ 7:00 PM.3-5-96. BLM