

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

AUG - 2 1993

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
V-737

7. Lease Name or Unit Agreement Name

A. E. 36 State

8. Well No.

1

9. Pool name or Wildcat

~~Avalon, E.~~ *Morrow*

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER Dry Hole

2. Name of Operator

Collins & Ware, Inc. ✓

3. Address of Operator

303 W. Wall, Ste. 2200, Midland, TX 79701

4. Well Location

Unit Letter E : 2180 Feet From The No. Line and 660 Feet From The West Line

Section 36

Township

20S

Range

28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3207.6 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 11696: Morrow perfs; 11623-11696. Set CIBP @ 11600' w/35' cement. Morrow perfs 11294'-11490'. Set CIBP @ 11200' w/35' cement. Strawn perfs; 10397'-10429'. Set CIBP @ 10280' w/4-25 sx plugs 6385-10280 TOC 6385. Delaware perfs 5298-5420; 179 shots; these are now open. Propose set CIBP @ 5250 w/35' cement plug on top. set 25sx plug @ 2899 to 2673. set 25sx plug @ 1360-1140. Set 25sx plug @ 470 to 226. 5sx @ surf. Install marker. Fluid used spotting plugs; 10# 30 Vis.

Csg. points 85/8 shoe @ 2786

133/8 shoe @ 1247

20" shoe @ 357

Cement calculated on all strings.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Max Guerry Max Guerry

TITLE

Regulatory Manager

DATE

7-29-93

TYPE OR PRINT NAME

TELEPHONE NO. 915-687-3435

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY

SUPERVISOR, DISTRICT II

TITLE

DATE

SEP 7 1993

CONDITIONS OF APPROVAL, IF ANY:

to witness