

DEC 13 1993

Form C-103
Revised 1-1-89Submit 3 Copies
to Appropriate
District OfficeState of New Mexico
Energy, Minerals and Natural Resources DepartmentDISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-27459
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Kansas City Singer 18
8. Well No.	1
9. Pool name or Wildcat	McMillan (Morrow)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole	
2. Name of Operator Santa Fe Energy Operating Partners, L.P. ✓	
3. Address of Operator 550 W. Texas, Suite 1330, Midland, Texas 79701	
4. Well Location Unit Letter <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>860</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>20S</u> Range <u>27E</u> NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3354.3' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Plugging witnessed by Mike Stubblefield w/ OCD.

11/08/93: Notified OCD (Ray Smith) of beginning plugging operations.
 11/09/93: Pull out of hole w/ tubing.
 11/10/93: Set CIBP @ 5470'. RIH w/ tubing and circ hole w/ 9.5 ppg mud. Spot 20 sx cement on top of CIBP. POH w/ tubing. RU hydraulic jacks on casing.
 11/11/93: Free-point casing at 2650'. Cut-off 5-1/2" casing at 2700' and pulled same. RIH w/ tubing to 3025'. Spot 65 sx cement at 3025'. WOC.
 11/12/93: RIH w/ tubing. Tag plug at 2570'. Spot 50 sx cement at 2568'. Spot 30 sx cement plug at 455'. Spot 15 sx cement plug at 50'. Cut-off casinghead and installed plate on casing. Installed dry hole marker.
 11/13/93: Cleaned up location. Well plugged and abandoned on 11/12/93.

Note: All cement plugs displaced w/ 9.5 ppg mud. All cement was Class "C" mixed to 14.8 ppg, yield 1.32.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 12/9/93
 TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 2/24/94
 CONDITIONS OF APPROVAL, IF ANY: