

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

WAGON UNIT #1 - V-3070
1980' FNL & 1980' FEL (Unit G)
Section 32-T22S-R23E
Eddy County, NM

DRILL STEM TESTS:

DST #1 9362-9414' Morrow: TIMES: 15", 60", 60", 120", 60". RECOVERY: 120' (.59 bbls) drilling mud, C1 67000 top, 67000 middle, 67000 bottom. SAMPLER: 15 psi @ 60 deg; .004 cfg, 2550 cc mud, c1 67000. PRESSURES: Depth 9373', IHP 4707, IFP 176-176, ISIP 219, 2nd FP 205-205, 2nd SIP 249, FFP 234-234, IHP 4707.

DST #2 9559-9614' Morrow: TIMES: 15", 60", 60", 120", 60". RECOVERY: 93' (1.3 bbls) drilling mud, 1134' (7.3 bbls) formation water, C1 62000 top, 57000 middle, 57000 bottom. SAMPLER: 490 psi @ 60 deg; .29 cfg, 2400 cc water, 56000 C1 .12 Rw @ 60 deg. PRESSURES: Depth - 9564', IHP 4775, IFP 264-311, ISIP 3486, 2nd FP 288-382, 2nd SIP 3486, FFP 382-524, FHP 4707.

DST #3 9666-9795' Morrow: TIMES: 15", 60", 60", 120", 60". RECOVERY: 240' (1.17 bbls) of rathole mud, C1 63000. SAMPLER: .67 cfg, 1000 cc mud, C1 63000. PRESSURES: Depth - 9677', IHP 4795, IFP 146-205, ISIP 380, 2nd FP 205-244, 2nd SI 321, 3rd FP 244-244, FHP 4975.