

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-27463
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3070
7. Lease Name or Unit Agreement Name Wagon AOG State
8. Well No. 1
9. Pool name or Wildcat Wildcat Yeso

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TITE HOLE <input type="checkbox"/>	RECEIVED
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	JUN 15 1994
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 32 Township 22S Range 23E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4283' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Testing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-28-94 - Swabbed. Shut well in.  
5-31-94 - Swabbed. Shut well in.  
6-1-94 - Load tubing with 2% KCL water. Unset packer. Drop down and unset RBP. Drop down and reset RBP at 2202'. Tested to 2000#. TOOH with 2-7/8" tubing and packer. Rig up wireline. TIH w/4" casing guns and correlated into place. Perforated 2120-2153' with 16 .42" holes (2 SPF) as follows: 2120, 22, 23, 28, 44, 46, 47 & 2153'. TOOH with casing guns and rig down wireline. TIH w/packer and 2-7/8" tubing. Spot 2 bbls 15% NEFE acid at 2183'. Pulled up and set packer at 2090'. Acidized perforations 2120-2153' with 3000 gallons 15% NEFE acid and ball sealers. Swabbed. Shut well in.  
6-2-94 - Swabbed. Shut well in.  
6-3-94 - Unset packer. Dropped down and unset RBP. TOOH with 2-7/8" tubing, packer and RBP. TIH w/2-7/8" tubing. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 6-14-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 15 1994