

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-78214
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., of Survey Description) 1980' FSL & 1980' FWL of Section 9-T22S-R24E (Unit K, NESW)	8. Well Name and No. Anemone ANE Federal #1
	9. API Well No. 30-015-28041
	10. Field and Pool or Exploratory Area Undesignated Canyon
	11. County or Parish, State Eddy Co., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent <input type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Abandonment <input checked="" type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input type="checkbox"/> Altering Casing <input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water <small>(No report results of multiple completion on Well Completion or Recompletion Report and Log form)</small>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
Propose to abandon Morrow completion and recomple to Canyon as follows:

1. Rig up wireline. Set standing valve in profile nipple at approximately 9990'. Blow tubing down and load with KCL water.
2. Nipple down tree, nipple up BOP. Unlatch tubing from on/off tool and TOOH. RIH w/RBP and set at 9950'. Test to 2000 psi. TOOH with tubing. NOTE: May set 2 sacks of sand on RBP.
3. Perforate 7855-8006' w/30 holes (1 SPF - Canyon) as follows: 7855, 57, 59, 82, 83, 84, 88, 89, 90, 7908, 11, 12, 13, 27, 28 & 7929' (16 holes) and 7976, 78, 80, 82, 84, 86, 88, 90, 92, 94, 8000, 02, 04 & 8006' (14 holes).
4. TIH with tubing, packer and RBP. Straddle perforations 7976-8006' and acidize w/2000 gallons 20% NEFE HCL acid and ball sealers.
5. Straddle perforations 7855-7929' and acidize with 2000 gallons 20% NEFE HCL acid and ball sealers.
6. Straddle perforations 7855-8006' and acidize with 42000 gallons 20% NEFE HCL acid with ball sealers.
7. Swab. Put well on pump.

14. I hereby certify that the foregoing is true and correct

Signed *Rusty Klein* Title Production Clerk Date March 29, 1995

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____

Conditions of approval, if any: _____