

Attachment to 3160-5

Roaring Springs "14" Fed Com #2
Sec 14, T 21S, R 23E (B)
660' FNL & 1680' FEL
API # 30-015-28185

- 8-11-99 Rotate drlg from 10,011 to 10,590'.
- 8-12-99 Rotate drlg. from 10,590 to 10,641', circ btms up, spot lubribeads from 10,641 to 9,150', spot lubribeads from 9150-7750', POOH. GIH w/ coiled tbg to acid-wash formation to 10,641'.
- 8-13-99 Complete acid wash in 5 stages, POOH w/ coil tbg. POOH w/ TIW packer. GIH w/ Weatherford retrieving tool, pull loose whipstock, POOH.
- 8-15-99 Jet & clean pits. Release rig @ 6 am. WO completion.