

Primer Operating Inc.
 Gearing, Ind. 471
 32-21-22 - 0

13 3/4 c 400' c
 8 3/4 c 1923 c
 TD 7400'
 Rem 7160'
 Pop 6230'
 Abc 3825'
 Tech 3152'
 Sh 1460'

7160 100'
 6230 100'
 3825 100'
 8 3/4 shac 3024 Tagged c 1880
 1460 3024

It is impossible to see the
 I wasn't sure where the rock was
 is and they so didn't bring it
 c. the other. They should have
 the rock. We had a 2 in. wire
 & probably cut it the same way.

Raymond
 3-6-95