

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

NM OIL CONS COMMISSION  
Drawer DD  
Artesia, NM 88210

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SDX Resources, Inc.

3. Address and Telephone No.

P. O. Box 5061, Midland, TX. 79704 915/685-1761

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 2260' FEL, Unit 0, Sec. 5, T20S, R28E

5. Lease Designation and Serial No.

NM 83581

6. If Indian, Allottee or Tribe Name

--

7. If Unit or CA, Agreement Designation

--

8. Well Name and No.

Citog 5 Federal #2

9. API Well No.

30-015-28220

10. Field and Pool, or Exploratory Area

Und-QN-GR-SA

11. County or Parish, State

Eddy

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☒ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6/03/95 Depth 1868', encountered sulfur water. Unable to drill ahead. Water in top pay zone and SDX plans to move out cable tool rig and either

1) Move in rotary rig or

2) Plug and Abandon as follows:

a) Set 100' plug at 1800' & tag & load hole with mud laden fluid.

b) Set 100' plug 50' in and out of surface shoe at 265'

c) Set 50' surface plug.

RECEIVED

JUL 14 1995

OIL CON. DIV.  
DIST. 2

14. I hereby certify that the foregoing is true and correct

Signed (John Pool) Title Vice President Date 6/12/95

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA Title PETROLEUM ENGINEER Date 7/12/95

Conditions of approval, if any:

See attached. Also tag plug @ surface csg. shoe.