Form 3160-5 (August 1999)

UN. ED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

NM-76919

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				an, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				or CA/Agreement, Name and/or No.	
1. Type of Well X Oil Well Gas Well Other 2. Name of Operator Santa Fe Energy Resources, Inc.				8. Well Name and No. Roaring Springs "14" Fed Com #5 9. API Well No.	
3a. Address 550 W. Texas, Suite 1330, Midland, TX	3b. Phone No. (include as 915-686-6612	00 010	30-015-28302 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Surve (H), 1980' FNL and 660' FEL, Sec. 1		Dagger (Upper	Draw, South		
Proposed BHL: (E), 1980' FNL and 6	4, T-21S, R23E	Eddy	NM NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resur	me) Water Shut-Off	
X Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation	Well Integrity Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Recomplete Temporarily Abandon	Drill horizontal	
	Convert to Inject	ion Plug Back	Water Disposal	lateral	
Describe Proposed or Commpleted Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be field within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) 6-30-99 MIRU, kill well, POOH W/ pump. SI wait on drlg rig. 7-7-99 MI Patterson Rig #80 @ 6 am. Prepare to Spud Horizontal Lateral. 7-10-99 GIH W/ 6 1/8" ring gauge & jnk bskt to 7810', POOH. GIH W/ pkr, set top of pkr @ 7778', POOH. GIH W/ gyro, check orientation of pkr, POOH. 7-10-99 GIH W/ whipstock, starting mill, but sub & DP @ 1 am to Spud Horizontal Lateral. Set whipstock, top of whipstock 7769' RKB. Mill 16" @ 7769' W/ start mill, POOH. GIH W/ window mill, watermellon mill, bit sub. PU kelly, install rot head. Mill window & ream same. POOH. 7-12-99 RU steering tool. PU directional tools. GIH W/ BHA & bit. RU WL, run gyro to btm, seat tool. Drlg 7781-7813' W/ tools faced @ 270 deg Azimuth. RD gyro. 7-13-99 RUGIH W/ steering & seat. Drl 7813-7864', 25 deg left tool face. POOH W/ WL. TOOH, adjust motor up to 4 deg. 7-14-99 TIH W/ bit, 4 deg mtr & MWD, try to slide drl, mtr stalling, POOH W/ motor. Change out mtr & adjust to 4 deg. TIH slide drl 7864-7930'. 7-15-99 Slide drlg 7930-8049', POOH for new BHA. PU new BHA.					
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		Title			
Bill Keathly			Regulatory Specialist		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by	- TOLFORFEI	Title	TICE USE	Date	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.