Form 3160-5	LINITE		100 Miler.	S. D. H.	C S	
Form 3160-5 UNITED STATES (June 1990) DEPARTMENT OF THE INTERIOR			St. C. 191	Budget Bur	eau No. 1004-0135	
(Juie 1996)		ND MANAGEMENT			5. Lease Designation and Serial No.	
	SUNDRY NOTICES AND			1	tion and Serial No.	
_		NM - 04827 - B 6. If Indian, Allottee or Tribe Name				
	m for proposals to drill or			5. If Indian, Allot	tee of Tribe Name	
U	SE "APPLICATION FOR PE	RMIT - " for such proposa	ls			
SUBMIT IN TRIPLICATE					7. If Unit or CA, Agreement Designation NORTH INDIAN BASIN	
1. Type of Well Oil V Gas						
Well A well Other					8. Well Name and No. NORTH INDIAN BASIN UNIT	
2. Name of Operator		#15 9. API Well No. 30-015-28305 30				
Marathon Oil Co						
3. Address and Telephone N	30-015-28305					
P.O. Box 552 Midland, TX 79702 (915) 687-8449 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or exploratory Area	
	SOUTH DAGGER	SOUTH DAGGER DRAW UPPER PENN				
1980 FNL, 1830						
SECTION 2, T-21-S, R-23-E					11. County or Parish, State	
				EDDY	NM	
12. CHECK A	PPROPRIATE BOX(s)	TO INDICATE NATURE	OF NOTICE, REPO	RT, OR OTHER DA	TA	
TYPE OF SU	TYPE OF SUBMISSION TYPE OF ACTION			ON		
Notice o	f Intent	Abandonmen		Change of P	lans	
_		Recompletion		New Constu	action	
X Subsequ	ent Report	X Plugging Bac	k	Non-Routin	e Fracturing	
L_1		Casing Repair	r	Water Shut		
Final Ab	andonment Notice	Altering Casing		Conversion	Conversion to Injection	
		Other		Dispose Wa	-	
					s of multiple completion on Well	

Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug back Morrow and recomplete in Upper Penn

MIRU PU. Kill well. N/D wellhead, N/U BOPs. Pulled BPV. Released packer. POOH with tubing. RIH w/CIBP and set @ 9,206' w/15' cement. Perfed 7688'-7722', 7748'-7784', & 7798'-7812' w/2 JSPF. RIH w/7" PPI packer on 2-7/8" tubing to 7848'. Set PPI packer & drop PPI standing valve. Unset PPI packer and pull up to 7812'. Spot 500 gallons of 28% HCl acid to PPI packer. Reverse circulate acid to tank. Set PPI packer and treat perfs at 7812'-7688' in 2' increments w/125 gallons 15% HCL NEFE acid per foot for a total treatment volume of 10,875 gallons. SITP 300 psi. Swab back load & test. Release packer and POOH w/tubing. RIH w/submersible pump to 2800' and landed tubing at 7880'. R/D PU and put well on production.

		ACCEPTED FOR RECORD NOV E DECORD (CRIG. SGD.) GARY GOURLEY
14. I hereby certify that the foregoing is true and correct Signed	Title Engineer Technic	cian Date11/4/97
(This space for Federal or Sum office use) Approved by Conditions of approval, if any:	Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ROSWELL OFFICE HALINOA - 9 - 40 LEG